

Date	Expiration	Release	Page
07.2017	N/A	1	1(9)

ENGINE CONTROL MODULE (ECM) SOFTWARE UPDATES

Prevost and Volvo vehicles

REVISION : A THIS BULLETIN SUPERSEDES PREVIOUS VERSION.
 08-30-2017 Campaign completion label relocated to front junction box.

DESCRIPTION

The vehicles affected by this bulletin may be equipped with an improperly functioning on-board emission- related diagnostic system that violates California and Federal standards and regulations.

The issue pertains to certain OBD (On-Board Diagnostic) monitors that may not illuminate the Malfunction Indicator Lamp (MIL) at the required threshold limits. This issue has no impact on fuel economy, drivability, performance, or safety of the engines.

To correct this issue, software updates are available for Prevost Engine Control Modules (ECM) for model year 2013 D13 Engines.

Please contact your nearest Prevost Service Center or Prevost service manager and schedule an appointment to have the required repairs applied.

MODEL YEAR(S) AND VEHICLES INVOLVED

<i>NOTICE TO SERVICE CENTERS</i>	
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
H3-45 coaches Model Year : 2013 - 2014	From 2PCH33499 <u>DC712364</u> up to 2PCH33496 <u>EC712601</u> incl.
H3-45 VIP motorhomes Model Year : 2013 - 2014	From 2PCVS3490 <u>DC712369</u> up to 2PCVS3495 <u>EC712594</u> incl.
X3-45 coaches Model Year : 2014	From 2PCG33497 <u>EC735459</u> up to 2PCG33493 <u>EC735622</u> incl.
X3-45 VIP motorhomes Model Year : 2013 - 2014	From 2PCBS3493 <u>DC735485</u> up to 2PCBS3490 <u>EC735607</u> incl.
X3-45 VIP commercial use Model Year : 2014	From 2PCCS3497 <u>EC735494</u> up to 2PCC33499 <u>EC735624</u> incl.
XLII-45 Entertainer Model Year : 2013	From 2PCY33491 <u>DC735461</u> up to 2PCYS3498 <u>DC735489</u> incl.
9700 Volvo coaches Model Year : 2014	From 3CET2S222 <u>E5162000</u> up to 3CET2S223 <u>E5165486</u>

Emissions Recall

EC0017A

Date	Expiration	Release	Page
07.2017	N/A	1	2(9)
incl.			
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.			

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
85152363	Emissions Recall Completion Sticker (All)	1

EQUIPMENT NEEDED

Description	Qty
Premium Tech Tool (PTT) version 2.05.23 or higher	1
Vocom Diagnostic Connector 88890304	1
Communication Interface 88890300	1

NOTE
<ul style="list-style-type: none">- Using other interfaces may affect programming speed.- Check Premium Tech Tool version by clicking on Help tab and then click on "About Tech Tool".

PROCEDURE

 DANGER
<p>Prior to working on the vehicle, park vehicle safely, apply parking brake and set the ignition switch to the ON position with the engine not running.</p> <p>Do not attempt to repair or service this vehicle without having sufficient training, the correct service literature and the proper tools. Failure to follow this could make the vehicle unsafe and lead to serious personal injury or death.</p>

Software Update Procedure

Date	Expiration	Release	Page
07.2017	N/A	1	3(9)

You must read and understand the precautions and guidelines in Impact; Service Information, group 20, "General Safety Practices, Engines" before performing this procedure. If you are not properly trained and certified in this procedure, ask your supervisor for training before you perform it.

NOTE

Information is subject to change without notice. Illustrations are used for reference only, and may differ slightly from the actual vehicle being serviced. However, key components addressed in this information are represented as accurately as possible.

1. Verify service program eligibility by checking service program status in VDA.
2. Connect Premium Tech Tool (PTT) to the vehicle diagnostic connector using the 16 pin OBD cable 88890304 and Communication Interface 88890300. Connect the PC to a functional LAN or modem connection and a 120 Volt AC source.
3. Turn the ignition switch **"ON"**.
4. Log in to PTT and Identify Vehicle is displayed.
5. Once the vehicle has been identified, enter the Work Order Number information, then click Start Work.

Work Order Number

Enter a work order number or select a recently used work order number in the list.

Enter work order number:

Select a recently used work order:

Work Order No	User ID	Date
---------------	---------	------


Enter Notes:

Start Work Cancel


6. From the Main Menu, select Program and **then** Program Electronic Control Unit 1700-08-

Date	Expiration	Release	Page
07.2017	N/A	1	4(9)

03-39. Then click Start.




7. Select **EMS**.




8. Select Program to update the **EMS** with the latest software.

Date	Expiration	Release	Page
07.2017	N/A	1	5(9)



9. Certain conditions must be met to continue with programming: battery voltage above 10v, parking brake applied, and ignition key in ON position with engine not running. When all conditions have been met, click Continue to proceed with programming.



10. Select "I accept" to agree to the terms and press continue to proceed. **Note:** In the United States and Canada, the programming is NOT chargeable. An invoice will not be generated.

Date	Expiration	Release	Page
07.2017	N/A	1	6(9)

1700-08-03-39 Program control unit - Update software

The following control units will be programmed

Engine Control Module (EMS)

Chargeable programming

The software you are about to program is chargeable. If programming is performed using the software, an invoice will be generated.

Programming will be charged once even if multiple retries are needed.

The software has commercial part number

85136079 : Engine Control Module

The number can be used for price lookup in your focal system and will be specified on the invoice.

I accept 

Select I accept to agree to the terms Press Continue to proceed

11. If the software is already updated, this screen opens. Select Yes to reload existing software.

1700-08-03-39 Program Electronic Control Unit - Update software

The following Electronic Control Units will be programmed

Vehicle Part Number:

Confirmation

Reload software

There are no software updates for the selected Electronic Control Unit

Do you want to reload the existing software?



12. When the programming is complete, clear any diagnostic trouble codes (DTC) and Finish Work.

NOTE

Use a campaign completion label (85152363) to signify that the campaign has been completed, use a permanent type marker to write the recall number, the completion date (MM/DD/YYYY) and dealer code on the label. The label is to be applied to the inside of the Front Junction Box door of all Prevost

Emissions Recall

EC0017A

Date	Expiration	Release	Page
07.2017	N/A	1	8(9)

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevest's normal warranty. We will reimburse you 3/4 hour (0.75) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevestcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin EC0017A".

OTHER

VBC Bulletin	N/A
Fail Code	06.27-2
Defect Code	49
Syst. Cond	R
Causal Part	3092091

Access all our Service Bulletins on
<http://techpub.prevestcar.com/en/>

or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive our warranty bulletins by e-mail.



Prevest engages in a continuous program of testing and evaluating to provide the best possible product. Prevest, however, is not committed to, or liable for updating existing products.

