

PREVOST

WB24-29

BULLETIN

WARRANTY

October 2024

SECTION : 05 COOLING

EXPIRATION: October 2026 SUBJECT :

SURGE TANK INSPECTION

First Release

10-29-2024

APPLICATION

NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website. PREVOST CAR INC. Model VIN H3-45 coaches From 2PCH33498RC721726 up to 2PCH33498RC721807 incl. Model Year: 2024 H3-45 VIP motorhomes From 2PCVS3492RC721727 up to 2PCV33496RC721811 incl. Model Year: 2024 2PCG33492RC734001, 2PCG33495RC734008, X3-45 coaches 2PCG33491RC734023, 2PCG3349XRC736997, Model Year: 2024 2PCG33493RC736999. X3-45 VIP commercial use From 2PCCS3499RC734000 up to 2PCCS3496RC736996 incl. Model Year: 2024 X3-45 VIP motorhomes 2PCBS3499RC734011, 2PCBS3495RC736998. Model Year: 2024 This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, the surge tank may be non-compliant. It must be inspected and, if needed, replaced.

MATERIAL

Order kit **WB24-29-1** which contains the following parts, for **X3 models** (only if required):

Part No	Description		Qty
050519	SURGE TANK, X		1
504637	CABLE TIE, NYLON BLK (STD)	6	3
050617	DECAL, COOLANT VOLVO VCS-2B	CAUTION A ATTENTION CUIDADO A	1
050466	DECAL, M4 MOT COOLANT, VALVE E		1

Order kit **WB24-29-2** which contains the following parts, for **H3 models** (only if required):

Part No	Description		Qty
050239	SURGE TANK, H		1
504637	CABLE TIE, NYLON BLK (STD)	G	10
5001834	WASHER BEL N500 10.5X23X2.5		2
5001774	NUT HEX FL STO N500 M12-1.75		4

21021850	CLAMP V-BAND 5 INCH	2
21095726	GASKET V-BAND JOINT, 5 INCH	2
8631155	CABLE TIE 200X4.6 TREE MOUNT	1

Other parts that may be required. Note that these parts are not covered by this bulletin:

Part No.	Description	Qty
680098	LOCTITE 567 TEFLON, 250ML	AR
680110	TEFLON SEALANT TAPE, 1/2"	AR
685353	YELLOW TORQUE SEAL, 1 OZ	AR
680335	LOCTITE 76764 ANTI-SEIZE	AR

NOTE	
Material can be obtained through regular channels.	

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:





PROCEDURE




Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance, or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.







- 11. Use a caliper to measure the bead diameter.
- If the bead diameter is less than **1.05 in**, the surge tank needs to be replaced.

NOTE


Make sure to perform steps 12 to 23 of this section and order the kit before proceeding to the surge tank replacement section.


- If the bead diameter is comprised between **1.05** in and **1.07** in, go to the next step.
- 12. Reconnect the hose to the surge tank.


13. Tighten the hose clamp to **30 lb-in**.


NOTE


The hose clamp must be pointing towards the rear of the vehicle as shown in the figure.




















- 11. Check the surge tank tube.
- If no bead is present, the surge tank needs to be replaced.

NOTE


Make sure to perform steps 21 to 33 of this section and order the kit before proceeding with the surge tank replacement section.


- If a bead is present, go to the next step.
- 12. Use a caliper to measure the bead diameter.
- If the bead diameter is less than **1.05 in**, the surge tank needs to be replaced.


NOTE


Make sure to perform steps 21 to 33 of this section and order the kit before proceeding to the surge tank replacement section.


- If the bead diameter is comprised between **1.05** in and **1.07** in, go to the next step.
- 13. Unscrew the bolts (2x) of the filler neck plate. Keep the hardware for reinstall.






























8. Unscrew the hose clamp and disconnect the recovery tank hose from the surge tank. C 9. Unscrew the hose clamp and disconnect the coolant return hose from the surge AC tank. 050463 10. Unscrew and disconnect the radiator hose from the elbow adapter on the surge tank. Do not unscrew the hose clamp.







17. Unscrew and remove the sight glass.	
18. Cut the cable ties (2x) securing the coolant level sensor harness.	
19. Unscrew and remove the coolant level sensor.	











34. Apply Loctite 567 thread sealant 680098 15° on the fitting threads that will be connected to the pressure relief port. 35. Reinstall the pressure valve assembly on the surge tank. NOTE Make sure hose fittings on valve assembly are positioned at 15° angle to the vertical. 36. Reconnect the overflow hose to the surge tank. 37. Tighten the hose clamps to **30 lb-in** (2x). 38. Attach the surge tank to its bracket on the vehicle with the T-bolt clamps. 39. Tighten the clamps. NOTE D MIL The T-bolts must be pointing towards the rear of the vehicle as shown in the figure.
















4. Press the release lever and push the DPF access hatch up until it locks in place. CAUTION Allow engine and exhaust aftertreatment system to cool down before proceeding with the following steps. 5. Open the pressure relief valve. ۲ n h 6 115 8 () 6. Remove the protection cap at the bottom of the radiator water pipe and connect the coolant extractor to the drain cock. 7. Drain the engine coolant.






















34. Cut the cable ties (2x) securing the coolant level sensor harness.	
35. Unscrew and remove the coolant level sensor from the surge tank.	
36. Unscrew the hose clamps (2x) and disconnect the sight glass tube from the surge tank.	
















 58. Reconnect and tighten the engine hose to the surge tank. <i>NOTE</i> The hose clamp must be pointing as shown in the figure. 	
 59. Reconnect and tighten the transmission hose to the surge tank, if applicable. <i>NOTE</i> This step is applicable only for vehicles equipped with the world transmission output retarder.	
60. Reconnect the hose, which is connected to the pump inlet pipe, to the surge tank.	
61. Tighten the hose clamp to 30 lb-in .	
NOTE The hose clamp must be pointing as shown in the figure.	




















PARTS / WASTE DISPOSAL

Replaced surge tanks must be returned to Prevost according to the Return Shipping Instructions available on <u>https://www.prevostcar.com/content/warranty-documents</u> for full reimbursement. A copy of the warranty claim form must be enclosed with the shipment.

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and labor as follows upon receipt of a warranty claim:

 $\frac{1}{2}$ hour (0.5) of labor for surge tank inspection only, for X3 models.

 $\frac{3}{4}$ hour (0.75) of labor for surge tank inspection only, for H3 models.

2 hours (2.0) of labor for surge tank inspection and replacement for X3 models.

2 ³/₄ hours (2.75) of labor for surge tank inspection and replacement for H3 models.

Please submit claim via our Online Warranty System, available at <u>www.prevostcar.com</u> (under Service \ Warranty section).

• Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-29 ".

OTHER

VBC Bulletin	N/A
Fail Code	05.07
Defect Code	09
Syst. Cond	В
Causal Part	050239 050519

Access all our Service Bulletins on *http://techpub.prevostcar.com/en/* or scan the QR-Code with your smart phone.

Are you a Vehicle owner? *E-mail us at* technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.

