

APPLICATION

Model	VIN		
H3-45 Coaches	2PCH3	334907C71 0698	2PCH33497AC71 1581
Model Year : 2007 - 2010		334988C71 <u>1096</u>	2PCH33490AC71 <u>1616</u>
	2PCH3	334989C71 <u>1357</u>	2PCH33499AC71 <u>1646</u>
	2PCH3	334939C71 <u>1363</u>	2PCH33490AC71 <u>1664</u>
	2PCH3	334979C71 <u>1379</u>	2PCH33496AC71 <u>1667</u>
	2PCH3	334979C71 <u>1446</u>	2PCH33498AC71 <u>1668</u>
X3-45 Coaches	2PCG3	3349X9C72 9614	2PCG33493AC72 <u>9815</u>
Model Year : 2009 - 2010			
The owners of the vehicles affected by this recall will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.			

DESCRIPTION

On the vehicles affected by this campaign, it is necessary to replace the accelerator pedal throttle position sensor as explained in the following procedure. This replacement is necessary only for vehicles equipped with Volvo D13 engine.

FAILURE CAUSE: Voltage applied by Volvo engine ECU exceeds the sensor capacity. Do not keep the throttle position sensor for later use as a sudden failure is very likely to happen.


FAILURE CONSEQUENCE: Faulty throttle position sensor causes the accelerator pedal to be inoperative due to a permanent idle signal. This leads to a vehicle breakdown with no response from the accelerator pedal.

MATERIAL

Order the following part:


Part No.	Description	Qty
568084	Sensor, accelerator pedal throttle position	1
NOTE		
Material can be obtained through regular channels.		

PROCEDURE



	sensor on the accelerator pedal assembly.	THROTTLE POSITION SENSOR / POTENTIOMÈTRE
2. 3.	Disconnect harness from sensor. Unscrew sensor fasteners (2) and remove throttle position sensor. Return sensor to Prevost for reimbursement.	CONNECTOR / CONNECTEUR SCREWS / VIS
4.	Make sure the rotary piece at the center of the new throttle position sensor is completely turned counterclockwise prior installation, if not, stationary regenerations might be impossible to initiate.	

- 5. Position new throttle position sensor on pedal assembly, secure with screws provided in the kit (torque to 25 lb-in).
- 6. Connect wiring harness to throttle position sensor. Secure wiring harness as originally routed.
- Start the engine. With the parking brake applied and transmission in neutral position (N), test the accelerator pedal for proper functioning.



WARRANTY

This modification is covered by Prevost's normal warranty. The working time required to perform this safety recall is between 15 to 30 minutes. We will reimburse you the parts and labor upon receipt of the replaced throttle position sensor and a completed A.F.A. form on which you must specify as per "Safety Recall SR12-16".

You also have to fill the 'Safety Recall Certification Sheet' provided with this bulletin and return it with your A.F.A. form to be reimbursed.

Parts / Waste disposal:

Return replaced parts to Prevost with A.F.A. for full reimbursement.

Please, identify the returned part with Prevost part number 531402.

OTHER

VBC Bulletin	N-A
Fail Code	03-08
Defect Code	9
System Condition	R
Causal Part	531402







PREVOS

SERIAL NUMBER: _____

PERFORMED BY	OWNER/OPERATOR
We hereby certify that Safety Recall Instructions with regard to Safety Recall #12-16 have been performed.	
Name:	Name:
Addr:	Addr:
Phone:	Phone:
Fax:	Fax:
Signature :	Signature :
Date:	Date:

If the information mentioned above is incorrect or you are not the owner of this vehicle anymore, please fill this section and return to sender.

Please return this completed document with your A.F.A. form