SP22-301A

Date Expiration Release Page 02.2022 02.2024 2 1(2)

Revision: A Connection points on top of the fuses added to the

procedure

03-01-2022

LOOSE CONNECTIONS ON ALTERNATOR CABLES - MAIN POWER COMPARTMENT

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, perform the following procedure to remedy four (4) potentially loose connections in the main power compartment.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

Model	VIN	Fleet Number
X3-45 Commuter Model Year: 2021 - 2022	Specific vehicles within the following range From 4RKJ33492 <u>M</u> 973 <u>7751</u> up to 4RKJ33499 <u>N</u> 973 <u>7957</u> incl	From 1300 up to 1548, incl.

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery.

MATERIAL NEEDED

The following parts:

Part No.	Description	Qty
504637	CABLE TIE, NYLON	4
5001341	WASHER, FLAT	4
5001787	NUT, NYRT SS M8-1.25X9.5	4

SP22-301A

 Date
 Expiration
 Release
 Page

 02.2022
 02.2024
 2
 2(3)

REQUIRED TOOLS

YELLOW TORQUE SEAL	RATCHET AND SOCKET SET – METRIC
TORQUE- SEAL® TORQUE-	
TORQUE WRENCH	

NOTE	
Material can be obtained through regular channels.	

Date	Expiration	Release	Page
02.2022	02.2024	2	3(4)

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



Date	Expiration	Release	Page
02.2022	02.2024	2	4(5)

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

1. In the main power compartment, remove the three (3) nylon ties identified on Figure 1.




Figure 1: three cables, two connection points

2. Unscrew and discard two (2) nuts identified on Figure 2. Clean any residue of torque marks on the studs, lugs and fuse bus bars.

Date Expiration Release Page 02.2022 02.2024 2 5(6)



Figure 2

3. Inspect the lugs, the studs and the fuse bus bars for damages. **If heat damage is evident**, **STOP AT THIS STEP** and contact immediately the Prevost field service manager and NYCT representative to further inspect the damage.

Example of damage: wear, heat effect, damaged parts, no coating on bus bars where the terminal sit or glue residue, among others.



Figure 3: cable lug in good condition, no heat effects

4. **FIRST CONNECTION POINT** (Figure 4). Reinstall the components in the proper sequence i.e. fuse bus bar, cable lug F101, cable lug ALTLL, washer and then the nylon insert nut (Figure 5).

 Date
 Expiration
 Release
 Page

 02.2022
 02.2024
 2
 6(7)




Figure 4: connection point: 1st & 2nd



Figure 5: 1st connection point

SP22-301A

Date Expiration Release Page 02.2022 02.2024 2 7(8)

5. Secure the two (2) cable lugs using one (1) washer no 5001341 and a nylon insert nut no 5001787. Tighten to a torque of 100 lbs-in.

IMPORTANT FOR LARGE CABLES: hold firmly the lug on the fuse during tightening as seen on Figure 6. Make sure contact between lug and bus bar is perfectly flat (Figure 7).

NOTE: Make sure there is no gap between the two terminal lugs. Make sure the 2 cables are sitting flat.



Figure 6





Figure 7: cable lug flat on bus bar

Date Expiration Release Page

02.2022 02.2024 2 8(9)

6. **2ND CONNECTION POINT** (Figure 8). Reinstall the components in the proper sequence i.e., fuse bus bar, cable lug ALTUR, washer and then the nylon insert nut (Figure 6).



Figure 8: 2nd connection point

7. Secure the cable lug using one (1) washer no 5001341 and a nylon insert nut no 5001787. Tighten to a torque of 100 lbs-in.

IMPORTANT FOR LARGE CABLES: hold firmly the lug on the fuse during tightening as seen on Figure 6. Make sure contact between lug and bus bar is perfectly flat (Figure 7).

8. The cables arrangement in the passthrough should look as seen on Figure 9.



Figure 9

Date Expiration Release Page

02.2022 02.2024 2 9(10)

9. Make sure that the three (3) cables are properly secured to the studs. No movement or rotation is allowed. Push/pull lightly on the cables, you should not feel any loose, the whole fuse block should move with the cables.

10. Install three (3) nylon ties no. 504637 as shown on Figure 10.



Figure 10

11. Inspect once again the contact between lugs and fuse bus bars.

- a) If OK, apply yellow torque seal marks.
- b) If not OK, redo the sequence, check and finally apply yellow torque seal marks.

Date

Expiration

Release

Page

02.2022

02.2024

2 10(11)

12. **3RD & 4th CONNECTION POINTS.** Repeat the same process for the 3rd & 4th connection points located on top of the same two (2) fuses. See Figure 11.




Figure 11: connection point: 3rd & 4th

- 13. Remember to report any other loose connections of **power cables** with VIN to Prevost field service manager and NYCT representative.
- 14. Remove the lockout/tag out, start the engine and confirm charging voltage.

SP22-301A

Date

Expiration

Release

Page

02.2022

02.2024

2

11(11)

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State [Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is $\frac{3}{4}$ hour (0.75 h).

OTHER

VBC Bulletin	N/A
Fail Code	06.21
Defect Code	09
Syst. Cond	В
Causal Part	5001787

Access all our Service Bulletins on http://techpub.prevostcar.com/en/

or scan the QR-Code with your smart phone.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.