

PREVOST


WARRANTY BULLETIN

WB24-23B

DATE :	July 2024	SECTION:	06 ELECTRICAL
EXPIRATION:	July 2026		
SUBJECT:	CB5 BREAKER INSPECTION		

Revision: B	VIN number clarification	07-02-2025
Revision: A	Part list change	11-01-2024

APPLICATION







NOTICE TO SERVICE CENTERS <i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN 
X3-45 coaches Model Year: 2023 - 2024	From 2PCG33496PC736900 up to 2PCG33493PC736935 incl. From 2PCG33493RC736937 up to 2PCG33493RC736999 incl.
X3-45 VIP commercial use Model Year: 2023 - 2024	From 2PCCS3495PC736890 up to 2PCCS3493PC736905 incl. From 2PCCS3493RC736907 up to 2PCCS3496RC736996 incl.
X3-45 VIP motorhomes Model Year: 2023 - 2024	2PCBS3495PC736898 / 2PCBS3492RC736974 2PCBS3491RC736979 / 2PCBS3490RC736990
H3-45 coaches Model Year: 2024	From 2PCH33496RC721496 up to 2PCH33497RC721782 incl.
H3-45 VIP motorhomes Model Year: 2023 - 2024	2PCVS3491PC721554 From 2PCVS3496RC721598 up to 2PCVS3491RC721783 incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION

On the vehicles affected by this bulletin, inspect breaker CB5 and replace it if need it.

MATERIAL

Order kit **WB24-23** which contains the following parts:

Part No	Description	Qty
563708	BREAKER 90A SENSATA 	1
502681	NUT HEX NYRT NX500 M6-1.0 G8 	2
5001936	NUT HEX NYRT NX500 3/8-16 	2
5000025	NUT HEX NYRT NX500 3/8-16 	4
5001787	NUT HEX NYRT SS M8-1.25X9.5 	1
5001789	NUT HEX NYRT SS M8 X 1.25 X 8 	1

Other parts that may be required. **Note that these parts are not covered by this bulletin:**

Part No.	Description	Qty
685353	YELLOW TORQUE SEAL, 1 OZ	AR

NOTE

Material can be obtained through regular channels.

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



Safety First!



PROCEDURE




DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.


Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

CB5 BREAKER INSPECTION X3 MODEL


1. Open compressor door.



2. Open rear junction box.




3. Locate CB5 breaker.




4. Verify if the breaker brand:


- If it is a **SENSATA** brand this ok, go to next step.
- If it is a **GLOSO** brand you need to replace it, go to breaker replacement section.



5. Close rear junction box door.




6. Close compressor door to complete the procedure.




CB5 BREAKER INSPECTION H3 MODEL

1. Open rear service compartment door on curbside.




2. Locate CB5 breaker.




3. Verify if the breaker brand:

- If it is a **SENSATA** brand this ok, go to next step.
- If it is a **GLOSO** brand you need to replace it, go to breaker replacement section.




4. Close rear service compartment door on curbside to complete the procedure.




CB5 BREAKER REPLACEMENT X3 MODEL


1. Open compressor door.




2. Turn off the switch of the main electrical.




3. Remove battery cover.




4. Disconnect battery ground.




5. Open rear junction box.




6. Locate CB5 breaker to replace.




7. Open the fuse holder **F101**.




8. Remove the nuts (2x) and the washers (2x).
9. Discard the nuts (2x) and keep the washers (2x) for reuse.




10. Remove the nuts (2x) and the washers (2x) and bus bar.
11. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse.




12. Remove the nuts (2x) and the washers (2x) and bus bar.
13. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse.




14. Remove the nuts (2x) and the washers (2x) and bus bar.
15. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse.




16. Remove the nuts (2x) and the breaker **CB5**.
17. Discard the nuts (2x) and the breaker **CB5**.



18. Install the new breaker CB5 563708 with new nuts 502681 (2x).




19. Tighten the nuts to **7 lb-ft** torque.




20. Reinstall bus bar with the new nuts 5000025 (2x) and the washers (2x).


Note: if you have difficulty installing the bus bar, loosen the nuts on the other circuit breakers.




21. Tighten the nuts to **140 lb-in** torque.
22. Apply torque seal 685353 on the nut.




23. Reinstall bus bar with the new nuts 5000025 (2x) and the washers (2x).




24. Tighten the nuts to **140 lb-in** torque.
25. Apply torque seal 685353 on the nut.




26. Reinstall bus bar with the new nuts 5001936 (2x) and the washers (2x).




27. Tighten the nuts to **140 lb-in** torque.
28. Apply torque seal 685353 on the nut.




29. Secure bus bar on the batteries relay with the new nut 5001789 (1x) and the washer (1x).




30. Tighten the nut to **100 lb-in** torque.
31. Apply torque seal 685353 on the nut.



32. Secure bus bar on the fuse holder **F101** with the new nut 5001787 (1x) and the washer (1x).



33. Tighten the nut to **125 lb-in** torque.
34. Apply torque seal 685353 on the nut.




35. Close the fuse holder **F101**.




F101

A technical line drawing of a vehicle's fuse block area. An orange rectangular fuse holder is shown being closed. A leader line points from the label 'F101' to the holder. Various wires and other components are visible in the background.


36. Close rear junction box door.




37. Reconnect battery ground.




38. Tighten the nut to **170 lb-in** torque.




39. Reinstall battery cover.



40. Turn on the switch of the main electrical.




41. Close compressor door.




CB5 BREAKER REPLACEMENT H3 MODEL


1. Open compressor compartment door.




2. Turn off the switch of the main electrical.




3. Open rear service compartment door on curbside.




4. Remove battery cover.




5. Disconnect battery ground.




6. Locate CB5 breaker to replace.




7. Open the fuse holder **F101**.




8. Remove the nuts (2x) and the washers (2x).
9. Discard the nuts (2x) and keep the washers (2x) for reuse.




10. Remove the nuts (2x) and the washers (2x) and bus bar.
11. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse..




12. Remove the nuts (2x) and the washers (2x) and bus bar.
13. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse.




14. Remove the nuts (2x) and the washers (2x) and bus bar.
15. Discard the nuts (2x) and keep the washers (2x) and bus bar for reuse.




16. Remove the nuts (2x) and the breaker **CB5**.
17. Discard the nuts (2x) and the breaker **CB5**.



18. Install the new breaker CB5 563708 with new nuts 502681 (2x).




19. Tighten the nuts to **7 lb-ft** torque.




20. Reinstall bus bar with the new nuts 5000025 (2x) and the washers (2x).


Note: if you have difficulty installing the bus bar, loosen the nuts on the other circuit breakers.




21. Tighten the nuts to **140 lb-in** torque.
22. Apply torque seal 685353 on the nut.




23. Reinstall bus bar with the new nuts 5000025 (2x) and the washers (2x).




24. Tighten the nuts to **140 lb-in** torque.
25. Apply torque seal 685353 on the nut.




26. Reinstall bus bar with the new nuts 5001936 (2x) and the washers (2x).




27. Tighten the nuts to **140 lb-in** torque.
28. Apply torque seal 685353 on the nut.




29. Secure bus bar on the batteries relay with the new nut 5001789 (1x) and the washer (1x).




30. Tighten the nut to **100 lb-in** torque.
31. Apply torque seal 685353 on the nut.



32. Secure bus bar on the fuse holder **F101** with the new nut 5001787 (1x) and the washer (1x).



33. Tighten the nut to **125 lb-in** torque.
34. Apply torque seal 685353 on the nut.




35. Close the fuse holder **F101**.


F101

A technical line drawing of a vehicle's fuse box area. A red rectangular fuse holder is shown in a partially open position. A leader line points from the label 'F101' to the holder. The holder is mounted on a metal plate with various other components and wiring visible in the background.


36. Reconnect battery ground.




37. Tighten the nut to **170 lb-in** torque.




38. Reinstall battery cover.




39. Close rear service compartment door.



40. Turn on the switch of the main electrical.



41. Close compressor compartment door.



PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and the part and labor as follows upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section).

- Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-23B".

Breaker inspection only

¼ hour (0.25) of labor

Breaker inspection and replacement

1 hour (1.0) of labor

OTHER

VBC Bulletin	N/A
Fail Code	06.16
Defect Code	09
Syst. Cond	B
Causal Part	564675

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>
 or scan the QR-Code with your smart phone.

Are you a Vehicle owner? E-mail us at
technicalpublications_prev@volvo.com and type "ADD" in the
 subject to receive warranty bulletins applicable to your vehicle(s)
 by e-mail.

