

PREVOST

WARRANTY BULLETIN

WB18-07B

	SUBJECT:	REVERSED BUSBAR AT CIRCUIT BREAKER CB13 - VEHICLES EQUIPPED WITH A CURRENT INVERTER		
l	EXPIRATION:	March 2020		
ı	DATE:	March 2018	SECTION:	06 ELECTRICAL

Revision: B

Part 1 – step 3, text removed: "just connect the ground cable (see part 4)". June 7, 2018

APPLICATION

ALLECATION						
	NOTICE TO SERVICE CENTERS					
	Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY					
STSTEM A	SYSTEM available on Service / Warranty tab of Prevost website.					
Model	VIN	VIA BEST AND				
H3-41, H3-45 coaches Model Year : 2018	2PCH33492 _J C71 3934					
X3-45 Commuter Model Year : 2017	4RKJ33498 <u>#</u> 973 <u>7386</u>					
	2PCG33492 G C73 5968	4RKG33491 <u>H</u> 973 7417				
	2PCG33490 <u>H</u> C73 <u>6182</u>	4RKG33493 <u>H</u> 973 <u>7418</u>				
	2PCG33496 <u>H</u> C73 <u>6185</u>	4RKG33495 <u>#</u> 973 <u>7419</u>				
	2PCG33491 <u>H</u>C73<u>6188</u>	4RKG33491 <u>H</u> 973 <u>7420</u>				
	2PCG3349X <u>#</u> C73 <u>6190</u>	4RKG33493 <u>H</u> 973 <u>7421</u>				
	2PCG33497 <u>H</u> C73 <u>6194</u>	4RKG33495 <u>#</u> 973 <u>7422</u>				
	2PCG33490 <i>H</i> C73 <u>6196</u>	4RKG33497 <u>H</u> 973 <u>7423</u>				
X3-45 coaches	2PCG33492 <u>H</u>C73<u>6197</u>	4RKG33499 <u>H</u> 973 <u>7424</u>				
Model Year : 2017 - 2018	2PCG33499 <u>H</u> C73 <u>6200</u>	4RKG33490 <u>H</u> 973 <u>7425</u>				
	2PCG33495 <u>#</u> C73 <u>6209</u>	4RKG33492 <u>H</u> 973 <u>7426</u>				
	2PCG33493 <u>J</u> C73 <u>6215</u>	4RKG33494 <u>H</u> 973 <u>7427</u>				
	2PCG33499 _ C73 6218	4RKG33496 <u>H</u> 973 <u>7428</u>				
	2PCG33499 _ C73 6221	4RKG33498 <u>H</u> 973 <u>7429</u>				
	2PCG3349X _J C73 <u>6227</u>	4RKG33497 _J 973 _7430				
	2PCG3349X _J C73 <u>6230</u>	4RKG33499 _J 973 <u>7431</u>				
	2PCG33490 <u>J</u> C73 <u>6236</u>	4RKG33490 <u>J</u> 973 <u>7432</u>				

	2PCG33492 _J C73 <u>6237</u>	4RKG33492 <u>J</u> 973 <u>7433</u>
	2PCG33496 _J C73 <u>6239</u>	4RKG33494 <u>J</u> 973 <u>7434</u>
	2PCG33491 _J C73 <u>6245</u>	4RKG33496 <u>J</u> 973 <u>7435</u>
	2PCG33493 _J C73 <u>6246</u>	4RKG33498 _J 973 7436
	2PCG33495 _J C73 <u>6247</u>	4RKG3349X _ 973 <u>7437</u>
	2PCG33497 _J C73 <u>6248</u>	4RKG33491 <u>J</u> 973 <u>7438</u>
	2PCG33497 _J C73 <u>6251</u>	4RKG33493 <u>J</u> 973 <u>7439</u>
	2PCG33499 _J C73 <u>6252</u>	4RKG3349X <u>J</u> 973 <u>7440</u>
	2PCG33490 _J C73 <u>6253</u>	4RKG33493 <u>J</u> 973 <u>7442</u>
	2PCG33492 _J C73 <u>6254</u>	4RKG33495 <u>J</u> 973 <u>7443</u>
	2PCG33496 _J C73 <u>6256</u>	4RKG33497 <u>J</u> 973 <u>7444</u>
	2PCG33491 _J C73 <u>6259</u>	4RKG33499 <u>J</u> 973 <u>7445</u>
	2PCG33498 _J C73 <u>6260</u>	4RKG33490 _J 973 <u>7446</u>
	2PCG3349X _J C73 <u>6261</u>	4RKG33492 _J 973 7447
	2PCG33493 _J C73 <u>6263</u>	4RKG33494 <u>J</u> 973 <u>7448</u>
		4RKG33496 <u>J</u> 973 <u>7449</u>
		4RKG33492 <u>J</u> 973 <u>7450</u>
		4RKG33494 <u>J</u> 973 <u>7451</u>
		4RKG33496 <u>J</u> 973 <u>7452</u>
		4RKG33498 <u>J</u> 973 <u>7453</u>
		4RKG3349X <u>J</u> 973 <u>7454</u>
		4RKG33491 _J 973 <u>7455</u>
		4RKG33493 <u>J</u> 973 <u>7456</u>
		4RKG33497 <u>J</u> 973 <u>7458</u>
		4RKG33493 <u>J</u> 973 <u>7473</u>
L		

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, the busbar connected to circuit breaker CB13 (power inverter) may have been installed reversely. It is necessary to check and to correct the installation if applicable. In the case of improper installation, it is also necessary to check if the threads of the circuit breaker stud are damaged.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

PART 1 - INSPECTION

1. Locate circuit breaker CB13.

NOTE

Usually, circuit breaker CB13 is installed in the main power compartment. On some vehicles, it is installed behind the mirror in the lavatory.




FIGURE 1 : CB13 IN THE LAVATORY, BEHIND THE MIRROR




FIGURE 2: CB13 IN MAIN POWER COMPARTMENT

- 2. Check if the busbar is installed correctly. The "flat" on the busbar must be placed on the circuit breaker located on the R.H. side of CB13.
- 3. If the busbar is installed properly, no further verification is necessary.

If the busbar is not installed properly, go to PART 2- CORRECTING THE INSTALLATION.





FIGURE 3: CORRECT INSTALLATION




Writer: E.L. <QF7720952_Rev 9>

PART 2 – CORRECTING THE INSTALLATION GROUND CABLE DISCONNECTION

4. Breaker CB13 is connected directly to the battery. Therefore, it is necessary to disconnect the ground cable reaching to the chassis at the battery installation in order to avoid any risk of short circuit during the removal and installation of the busbar.



FIGURE 5: DISCONNECT THE GROUND CABLE WHERE INDICATED WITH A CIRCLE



PART 3 - INSTALLING THE BUSBAR PROPERLY

 Remove the busbar and reinstall in accordance with the following criterion (see image at right):

The "flat" on the busbar must be placed on the circuit breaker located at the R.H. side of CB13.

Nut torque: 135 lbs-in (15 Nm)

IMPORTANT NOTE

- Replace the busbar if it is damaged, warped or cannot assure a good electrical contact with the surface of the circuit breaker.
 - busbar, part no 067465
- b) Replace circuit breaker CB13 if the stud or the threads are damaged and cannot assure an adequate tightening/clamping of the busbar. This circuit breaker could be a 150A or a 90A depending on the equipment installed. CAUTION: Replace with a circuit breaker of the same type/capacity.
 - circuit breaker CB13 150A, part no 568114

or

- circuit breaker CB13 90A, part no 563708
- c) Replace circuit breaker found at the right of CB13 if the stud or the threads are damaged and cannot assure an adequate tightening/clamping of the busbar. This circuit breaker could be a 150A or 50A. CAUTION: Replace with a circuit breaker of the same type/capacity.
 - circuit breaker 150A, part no <u>568114</u>

or

• circuit breaker 50A, part no <u>568127</u>





FIGURE 7

PART 4 – CONNECTING THE GROUND CABLE

6. Connect the ground cable.

Nut torque: 170 lbs-in (19 Nm)



PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and half an hour (0.5) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB18-07".

OTHER

VBC Bulletin	N/A	
Fail Code	06.06	
Defect Code	09	
Syst. Cond	В	
Causal Part	067475	

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.