

PREVOST

WARRANTY BULLETIN

WB24-27

DATE: August 2024 SECTION: 06 ELECTRICAL

EXPIRATION: August 2026

SUBJECT: HARNESS CONNECTORS MODIFICATION

First Release 08-27-2024

APPLICATION

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

STSTEM available of Service? Waltarity tab of Trevost Website.				
Model	VIN	VAN, RESERVENT CAR INC. PREVOST CAR INC. IT GLAW FOROIGHTR OF GRANA		
H3-45 coaches Model Year: 2023		2PCH33490 P C72 1359 2PCH33496 P C72 1382 2PCH33498 P C72 1402 2PCH33494 P C72 1431		
H3-45 coaches Model Year: 2024	Fro	om 2PCH3349X <u>R</u> C72 <u>1453</u> to 2PCH33497 <u>R</u> C72 <u>1782</u> incl.		

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, modify the connectors harness pin out and fuse.

MATERIAL


Order the following part:

Part No	Description	Qty
563153	FUSE ATM 25A	1

NOTE	
Material can be obtained through regular channels.	

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:




PROCEDURE




DANGER


Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.






9. Reinstall the cover of the DVEC.




- 10. Disconnect the connectors **VECR1** (gray) and **VECR2** (red).
- 11. Remove the secondary lock of both connectors.



12. Extract the terminal from the position **C** of the connector **VECR2** (red).



13. Insert the terminal at position **G** of the connector **VECR1** (gray)





- 14. Reinstall the secondary lock of both connectors.
- 15. Identify the wire of terminal **F130**.



16. Reconnect the connectors **VECR1** (gray) and **VECR2** (red).







PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and $\frac{1}{2}$ hour (0.5) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section).

• Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-27".

OTHER

VBC Bulletin	N/A
Fail Code	06.16
Defect Code	09
Syst. Cond	В
Causal Part	563153

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.