

PREVOST

WARRANTY BULLETIN

WB24-19

DATE: August 2024 SECTION: 22 HVAC

EXPIRATION: August 2026

SUBJECT: TEMPERATURE SENSOR RELOCATION

First Release 08-29-2024

APPLICATION

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

Model	VIN PROPERTY OF CAME PORTY IT OF CAME			
H3-45 VIP motorhomes Model Year: 2022	2PCVS3498 <u>N</u> C72 <u>1211</u> 2PCV33490 <u>N</u> C72 <u>1247</u> 2PCVS3491 <u>N</u> C72 <u>1258</u> 2PCVS349X <u>N</u> C72 <u>1274</u> 2PCVS3491 <u>N</u> C72 <u>1308</u>			
H3-45 VIP motorhomes Model Year: 2023 - 2025	From 2PCVS3499 <u>P</u> C72 <u>1348</u> up to 2PCV33490 <u>S</u> C72 <u>2037</u> incl.			

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin the temperature sensor must be relocated for better temperature control.

MATERIAL

Order kit **WB24-19** which contains the following parts:

Part No.	Description	Qty
455465	KIT AIR RETURN DEFROSTER SENSOR	1

WB24-19 Page 2 / 16

kit 455465 which contains the following parts:

Part No.	Description	Qty
0600352	EXTENSION CABLE HVAC SENSOR	1
3202184	SENSOR ADAPTOR PLATE	1
5001305	SCREW MACHINE ROUND PH SS 8-32X3/4	2
5002031	WASHER FLAT SS NSS 4.3X12X1	2
500678	NUT WELL 8-32X.450	2
504637	CABLE TIE, NYLON BLACK (STD)	5

Other parts that required. Note that these parts are not covered by this bulletin:

Part No.	Description	Qty
682484	TAPE ALUMINUM ADH1 .005" x 3" x 300'	

NOTE	
Material can be obtained through regular channels.	

WB24-19 Page 3 / 16

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.


Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

WB24-19 Page 4 / 16




CAUTION

If access to the air return grill was obstructed during the vehicle conversion. Please refer to the section "move the sensor if duct grill cannot be remove (option)".




WB24-19 Page 5 / 16



WB24-19 Page 6 / 16


8. Apply aluminum tape 682484 on the sensor hole. 682484 9. Remove the grill and screws (6x). 10. Use sensor adaptor plate as template. Center the plate in middle of the air duct. 11. Mark the position of the center of each **• • •** hole (3x). 12. Drill the pilot holes (3x).

WB24-19 Page 7 / 16




WB24-19 Page 8 / 16


17. Install the sensor inside the duct with the screws 5001305 (2x) and the washers 5002031 (2x).




18. Reinstall the grill with the screws (6x).



19. Connect the new sensor extension cable 0600352 connector **C21A** to **Se21** connector of the front harness




20. Run the new sensor extension cable 0600352 along air return pipe.




WB24-19 Page 9 / 16


21. Connect the new sensor extension harness 0600352 connector **C21AA** to the sensor.




22. Secure the harness 0600352 to the air return pipe with cable tie 504637 (5x).



23. Reinstall the top access panel with the screws (4x) inside the compartment.




24. Close the front bumper.




<QF7720952_Rev 13>


Writer: JPHD

WB24-19 Page 10 / 16







WB24-19 Page 11 / 16



WB24-19 Page 12 / 16




WB24-19 Page 13 / 16




WB24-19 Page 14 / 16


16. Install the sensor inside the duct with the screws 5001305 (2x) and the washers 5002031 (2x).




17. Connect the new sensor extension cable 0600352 connector **C21A** to **Se21** connector of the front harness



18. Run the new sensor extension cable 0600352 along air return pipe.




19. Connect the new sensor extension harness 0600352 connector **C21AA** to the sensor.




Writer: JPHD

WB24-19 Page 15 / 16


20. Secure the harness 0600352 to the air return pipe with cable tie 504637 (5x).




21. Reinstall the top access panel with the screws (4x) inside the compartment.



22. Close the front bumper.



23. Close front service door.



WB24-19 Page 16 / 16

PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and three hour(s) (3.0) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section).

Prevost is not responsible for any excess workload if access to the air return grill was obstructed during the vehicle conversion. Please refer to the Converter.

• Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-19".

OTHER

VBC Bulletin	N/A
Fail Code	22.01
Defect Code	09
Syst. Cond	В
Causal Part	564318

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.