

PREVOST

WARRANTY BULLETIN

WB24-30

DATE: September 2024 SECTION: 06 ELECTRICAL

EXPIRATION: September 2026

SUBJECT: REORGANIZING CONDENSER FAN POWER

DISTRIBUTION

First Release 09-06-2024

APPLICATION

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

Model	VIN PROGRAMMATION PREVIOUS CAR INC.
X3-45 coaches Model Year: 2024	From 2PCG33492RC734001 up to 2PCG3349XRC734117 incl.

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, reorganize the condenser fans power distribution.

WB24-30 Page 2 / 13

MATERIAL

Order kit WB24-30 which contains 0600595 which contains following parts:

Part No	Description		Qty
0600336	FUSE HOLDER FAN HARNESS		1
5001341	WASHER FLAT SS 8.4X16X1.6		1
5001787	NUT HEX NYRT SS M8-1.25X9.5		1
563153	FUSE ATM 25A	To ge o	4
564899	SMALL FUSE HOLDER		1
0600520	DECAL REAR JUNCTION BOX COMPONENTS		1
504637	CABLE TIE, NYLON BLK (STD)		10

Other parts that may be required. **Note that this part is not covered by this bulletin**:

Part No.	Description	Qty
685353	YELLOW TORQUE SEAL, 1 OZ	AR

NOTE	
Material can be obtained through regular channels.	

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:




PROCEDURE





DANGER


Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.












Locate the connectors VECR1 (gray),
VECR2 (red), VECR3 (black) and VECR4 (orange).




- Remove the connector lock position of connector VECR1.
- 20. Disconnect VECR1.
- 21. Remove the terminal lock position of the connector **VECR1**.
- 22. Remove the terminal **F143** at position **A** of connector **VECR1**.
- 23. Reinstall the terminal lock position of the connector **VECR1**.
- 24. Reconnect VECR1.
- 25. Reinstall the connector lock position assurance of connector **VECR1**.




- 26. Remove the terminal of F143.
- 27. Connect the wire **F143** to butt splice **F401** of new harness 0600336.
- 28. Heat the butt splice shrink sleeve.




- 29. Remove the connector lock position of connector **VECR2**.
- 30. Disconnect VECR2.
- 31. Remove the terminal lock position of the connector **VECR2**.
- 32. Remove the terminal **F144** at position **D** of connector **VECR2**.
- 33. Reinstall the terminal lock position of the connector **VECR2**.
- 34. Reconnect VECR2.
- 35. Reinstall the connector lock position assurance of connector **VECR2**.




- 36. Remove the terminal of F144.
- 37. Connect the wire **F144** to butt splice **F400** of new harness 0600336.
- 38. Heat the butt splice shrink sleeve.




- Remove the connector lock position of connector VECR3.
- 40. Disconnect VECR3.
- 41. Remove the terminal lock position of the connector **VECR3**.
- 42. Remove the terminal **F142** at position **C** of connector **VECR3**.
- 43. Reinstall the terminal lock position of the connector **VECR3**.
- 44. Reconnect VECR3.
- 45. Reinstall the connector lock position assurance of connector **VECR3**.



- 46. Remove the terminal of **F142.**
- 47. Connect the wire **F142** to butt splice **F402** of new harness 0600336.
- 48. Heat the butt splice shrink sleeve.




- 49. Remove the connector lock position of connector **VECR4**.
- 50. Disconnect VECR4.
- 51. Remove the terminal lock position of the connector **VECR4**.
- 52. Remove the terminal **F141** at position **E** of connector **VECR4**.
- 53. Reinstall the terminal lock position of the connector **VECR4**.
- 54. Reconnect VECR4.
- 55. Reinstall the connector lock position assurance of connector **VECR4**.




Writer: JPHD


- 56. Remove the terminal of F141.
- 57. Connect the wire **F141** to butt splice **F403** of new harness 0600336.
- 58. Heat the butt splice shrink sleeve.




59. Secure the new harness 0600336 with cable ties 504637(10X) on the existing harness.





60. Remove the rear junction box components decal.



61. Install the new rear junction box components decal 0600520.







PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and ¾ hour (0.75) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section).

• Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-30".

OTHER

VBC Bulletin	N/A
Fail Code	06.16
Defect Code	09
Syst. Cond	В
Causal Part	870246

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.