

PREVOST

ENREGISTRÉ-REGISTERED ISO 9001 & ISO 14001

SAFETY RECALL

Sr03-06



DATE: MARCH 2003 SECTION: 14

SUBJECT: INSPECTION OF STEERING COLUMN

UNIVERSAL JOINT FASTENERS

APPLICATION

Model	VIN	VIA RECURSION OF THE CONTRACT
H3-41, H3-45 Coach	Vel	nicle 2PCH33494 <u>W</u> 101 <u>2234</u> and also
Model Year : 1998 - 2003	from 2PCH33	49X <u>W</u> 101 <u>2285</u> up to 2PCH33494 <u>3</u> 101 <u>4738</u> incl.
XL2-45 Coach	From 2PCX33495 <u>Y</u> 102 <u>6951</u> up to 2PCX33492 <u>4</u> 102 <u>8151</u> incl.	
Model Year : 2000 - 2004		
H3-45 VIP Bus Shell,	From 2PCV33497 <u>W</u> 101 <u>2294</u> up to 2PCV33499 <u>3</u> 101 <u>4740</u> incl.	
Model Year : 1998 - 2003		
XL2-40, XL2-45 Bus Shell, Entertainer XL2	2PCW33496 <u>Y</u> 102 <u>6856</u> 2PCW33498 <u>Y</u> 102 <u>6924</u> and also	
Model Year : 2000 - 2003		
	from 2PCW33	491 <u>Y</u> 102 <u>6991</u> up to 2PCW33491 <u>3</u> 102 <u>8152</u> incl.

DESCRIPTION

Some of the above mentioned vehicles may have had their steering column universal joint yokes secured with replacement fasteners that do not meet the manufacturer specifications. A groove in the steering gearbox input shaft prevents the yoke from disengaging even if the fasteners torque is insufficient. If replacement fasteners torque not proper, this protection is not provided and the yoke could separate from the gearbox input shaft when a steering column adjustment is done, resulting in a lost of control.

All vehicles equipped with this steering column model have to be inspected. Part A of this recall describes how to check the fasteners. If the fasteners are not up to the manufacturer's specifications, they have to be replaced as explained in part B.

MATERIAL

Part No.	Description	Qty
661095	Bolt, meeting manufacturer's specifications	1
661096	Nut, meeting manufacturer's specifications	1

Note: Material can be obtained through regular channels.

PROCEDURE

Warning: Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

PART A: FASTENERS INSPECTION

Note: The lower steering column universal joint is accessible from the front service compartment and the upper one is accessible from the driver's compartment under the steering covers.

- 1. Locate the lower universal joint (figure 1) and check if the bolt and nut are up to the manufacturer's specifications. To do so, use a standard SAE 11/16 socket or a 17mm metric socket. If the dimensions of the nut and the bolt head fit with the socket, i.e. they could be tighten with the socket, they meet the manufacturer's specifications and they do not need to be changed. If they are too small and do not fit with the socket, they have to be changed according to part B of this recall.
- 2. From the driver's compartment area, remove the three plastic fasteners on steering column cover (figure 1). Remove the lower cover. Unscrew the four retaining screws on steering column middle cover. Unscrew the four retaining screws fixing steering column upper cover to middle cover. Remove the steering column middle and upper covers. Position the steering wheel in order to gain access to the joint. Check if the upper joint fasteners are up to the manufacturer's specifications as described in step 1.

PART B: FASTENERS REPLACEMENT

Note: Order the required fasteners. Use a new nut for each new bolt.

- 1. Remove the nut and bolt that need to be replaced. Do not dismount the joint yoke from the shaft.
- 2. Put the proper nut and bolt in place and tighten to a torque of 43 lbf-ft (60 N·m).
- Reinstall the steering column covers.




FIGURE 1: STEERING COLUMN

WARRANTY

The verification is covered by Prévost Car's normal warranty. We will reimburse you 1/4 hour (0.25) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Safety Recall 03-06 Part A" if no fasteners replacement was done. You also have to fill the "Safety Recall Certification Sheet" provided with this bulletin and return it with your A.F.A. form to be reimbursed.

We will reimburse you the parts and 1/2 hour (0.5) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Safety Recall 03-06 Part A & B" if a fasteners replacement was performed. You also have to fill the 'Safety Recall Certification Sheet' provided with this bulletin and return it with your A.F.A. form to be reimbursed.

Parts disposition:

- Discard according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)





Safety Recall Certification Sheet (Ref: Sr03-06)



SERIAL NUMBER:_					
PERFORMED BY	OWNER/OPERATOR				
We hereby certify that Safety Recall Instructions with regard to Safety Recall #03-06 have been performed.					
Sr03-06, Part A: YES					
Sr03-06, Part B: YES NO					
Name:	Name:				
Addr:	Addr:				
Phone:	Phone:				
Fax:	Fax:				
Signature :	Signature :				
Date:	Date:				
Date.	Date.				
If the information mentioned above is incorrect or you are not the owner of this vehicle anymore, please fill this section and return to sender					
NEW OWNER:					
BUSINESS:					
ADDRESS (including County):					
TELEPHONE: FAX:					

Please return this completed document with your A.F.A. form