WB11-54

| Date | Expiration | Group | No. | Page |
|---------|------------|-------|-----|-------|
| 09.2011 | 09.2012 | 65 | 1 | 1 (8) |

AIR SPRING MEMBER REPLACEMENT 9700 (B13R)


MODEL YEAR(S) AND VEHICLE SERIAL NUMBERS (VIN) INVOLVED

The following 2010 and 2011 year model 9700 are involved:

| 3CET2S229A5139243 | 3CET2S228B5143804 | 3CET2S22XB5143920 | 3CET2S228B5145729 | 3CET2S22XB5145926 |
|-------------------|-------------------|-------------------|-------------------|-------------------|
| 3CET2S221B5142235 | 3CET2S22XB5143805 | 3CET2S221B5143921 | 3CET2S224B5145730 | 3CET2S228B5146461 |
| 3CET2S223B5142236 | 3CET2S221B5143806 | 3CET2S223B5143922 | 3CET2S220B5145918 | 3CET2S22XB5146462 |
| 3CET2S225B5142237 | 3CET2S223B5143807 | 3CET2S225B5143923 | 3CET2S222B5145919 | 3CET2S223B5146464 |
| 3CET2S227B5142238 | 3CET2S224B5143914 | 3CET2S227B5143924 | 3CET2S229B5145920 | 3CET2S227B5146466 |
| 3CET2S229B5142239 | 3CET2S226B5143915 | 3CET2S229B5143925 | 3CET2S220B5145921 | 3CET2S225B5147664 |
| 3CET2S220B5143800 | 3CET2S228B5143916 | 3CET2S220B5145725 | 3CET2S222B5145922 | 3CET2S229B5148252 |
| 3CET2S222B5143801 | 3CET2S22XB5143917 | 3CET2S222B5145726 | 3CET2S224B5145923 | 3CET2S220B5148253 |
| 3CET2S224B5143802 | 3CET2S221B5143918 | 3CET2S224B5145727 | 3CET2S226B5145924 | 3CET2S226B5148659 |
| 3CET2S226B5143803 | 3CET2S223B5143919 | 3CET2S226B5145728 | 3CET2S228B5145925 | |

DESCRIPTION

On the vehicles affected by this bulletin, the left-hand and right-hand side air spring members are not compliant and have to be replaced as soon as possible and before the expiration of this bulletin. The new members can be recognised by the yellow dot they have and/or a sequence number of the casting, see pictures below.





| Date | Expiration | Group | No. | Page |
|---------|------------|-------|-----|-------|
| 09.2011 | 09.2012 | 65 | 1 | 2 (8) |

MATERIAL

| Part No | Description | Qty |
|----------|----------------------|-----|
| 21323411 | Air Spring Member LH | 1 |
| 21323412 | Air Spring Member RH | 1 |
| 907861 | Split pin 4x32 | 2 |
| 990962 | M16 Lock Nut | 4 |

PROCEDURE



DANGER

Before working on a vehicle, turn the vehicle ignition switch OFF, set the parking brakes, place the transmission in neutral, and block the wheels. Failure to do so can result in unexpected vehicle movement and can cause serious personal injury or death. When disconnecting battery cables, disconnect the ground (negative) cable first to prevent personal injury from electrical shock.

| 1. | Block the front wheel tires. | |
|-------|--|--|
| 2. | Lift up the vehicle with a hydraulic jack and jack up the frame in front of and behind the rear axle. It is not necessarily to remove the tires. <u>In fact the tires</u> <u>should have contact with the floor as a</u> <u>support for the drive axle.</u> | |
| butte | Release the drive axle bellows (air spring) air pressure. To do so, you can: s the lower part of the bus level control on or onnect the valve block ECS drive axle. | |

4.

5.

6.



| - | | | | | |
|---|------------------------|--------------------|-------------|----------|----------------------|
| | Date 09.2011 | Expiration 09.2012 | Group 65 | No. 1 | Page 3 (8) |
| Disconnect the air suspension level sensor rod from the member. | | | | | |
| Remove the shock absorbers lower nuts. Take care of the rubber bushings and washers. | | | | | |
| Remove the split pin and loosen the lower ball joint to anti-roll bar from the member. Compress the shock so it looses its location in the member. | | | | | DIAL. |



| | | | | | | <u> </u> |
|----|--|------------------------|------------------------------|-------------|----------|----------------------|
| | | Date 09.2011 | Expiration 09.2012 | Group 65 | No. 1 | Page 4 (8) |
| _ | | 05.2011 | 05.2012 | 05 | I | 4 (0) |
| 7. | Loosen and remove washer and screws securing the reaction rod to the member. | | | | | |
| 8. | Loosen the bolts for the frame anchorage reaction rod. Remove the reaction rod. Take care of the shims. Identify the reaction rods with its origin place (left, right) so they end up on the same side even after the repair. | | | | | T |
| 9. | Place two hydraulic jacks under the member, one at the front and one at the rear. | | | | | |



| | | Date 09.2011 | Expiration 09.2012 | Group 65 | No. 1 | Page 5 (8) |
|-----|--|------------------------|--------------------|--------------------|----------|----------------------|
| 10. | Loosen and remove the bolts for the member anchorage to the drive axle. Lower the member using the jacks and remove the member. | | | | 1502/201 | |
| 11. | Place the new Air Spring Member on the jacks and lift it in to position. Make sure the locating pin in the member lines up with the locating hole in the rear axle. | | | | | |
| 12. | Tighten the bolts in sequence in three steps. Step one 300Nm (221 lbf-ft) Step two 550Nm (406 lbf-ft) Step three 685Nm (505 lbf-ft) | | | 2 | | |



| | Date 09.2011 | Expiration 09.2012 | Group 65 | No. 1 | Page 6 (8) |
|--|--|--------------------|--------------------|----------|----------------------|
| 13. Mount the ball joint for the anti-roll bar to the Member. Torque it to 200Nm (148 lbf-ft) and fit a new split pin (part # 907861). | | | | | |
| 14. Reassemble the reaction rod. Torque the bolts on the member to 85Nm (63 lbf-ft). | | | | | |
| 15. Use new flange lock nuts 990962 for the reaction rod. Torque the reaction rod to the frame at 220Nm (162 lbf-ft). Do not forget to put the shims back in position. | Received and a second s | | | | |
| 16. Reassemble the lower anchorage for the shock absorbers and tighten the nut to 115Nm (85 lbf-ft). | | | | | |

17.

18.

19.

20.



| | Date 09.2011 | Expiration 09.2012 | Group 65 | No. 1 | Page 7 (8) |
|---|------------------------|---------------------------|--------------------|----------|----------------------|
| Assure that the air bellows are in the right position. Fill the drive axle bellows with air. | | | | | |
| Lift up the vehicle with hydraulic jack and remove the jacks. | | | 1 | | |
| | | | | | 100 |
| Start the vehicle and let the air pressure buil if necessarily. | d up. Check | the height of | f the air be | ellows, | adjust |

<QF7720962_1> Warranty Bulletin (Volvo Brand) - [Diffusé] No. Révision: 2 - Date de diffusion: 2011-06-22 15:34:23



| Date | Expiration | Group | No. | Page |
|---------|------------|-------|-----|-------|
| 09.2011 | 09.2012 | 65 | 1 | 8 (8) |

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you 3.5 hours with two technicians for a total of seven (7) hours of labor upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 11-54".

TELL US WHAT YOU THINK!

We are interested in hearing your comments or suggestions regarding this bulletin. Please e-mail them to: TechnicalPublications@volvo.com

OTHER

| VBC Campaign | S8733 |
|------------------|----------|
| Fail Code | 16-00 |
| Defect Code | 00-09 |
| System Condition | В |
| Causal Part | 21323411 |

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Volvo Bus, however, is not committed to, or liable for updating existing products.