

WARRANTY BULLETIN

WB15-19H

REVOST

DATE :OCTOBER 2015SECTION :22 - HVACEXPIRATION:OCTOBER 2017

SUBJECT :

BITZER A/C COMPRESSOR VIBRATION – ADDITION OF A REINFORCEMENT BRACKET TO THE MOUNTING

Rev H: THIS WARRANTY BULLETIN SUPERSEDES PREVIOUS VERSIONS

Released: April 2018

Lang electromagnetic clutch extractor/puller was #7770159, changed for #680888.

APPLICATION

NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.			
Model	VIN		
H3-41, H3-45 coaches Model Year : 2013 - 2015	And from 2PC	2PCH33494 <u>D</u> C71 <u>2272</u> H33499DC71 <u>2364</u> up to 2PCH33495FC71 <u>2994</u> incl.	
H3-45 VIP motorhomes Model Year : 2013 - 2015	2PCVS3499 <u>D</u> C7 2PCVS3494EC7 2PC And from 2PC	The following individual vehicles: 1 <u>2399</u> , 2PCVS3499 <u>D</u> C71 <u>2452</u> , 2PCVS3490EC71 <u>2468</u> , 1 <u>2473</u> , 2PCVS3490EC71 <u>2549</u> , 2PCVS3496EC71 <u>2555</u> , VS3493EC71 <u>2612</u> , 2PCVS3495EC71 <u>2689</u> VS3495FC71 <u>2709</u> up to 2PCVS349XFC71 <u>2950</u> incl. equipped with Bitzer A/C compressor	
X3-45 coaches Model Year : 2013 - 2016	2PC From 2PCG	G33491 <i>D</i> C73 <u>5388</u> , 2PCG33492 <i>D</i> C73 <u>5433</u> 33497EC73 <u>5459</u> up to 2PCG33494GC73 <u>5910</u> incl.	
X3-45 VIP motorhomes Model Year : 2014 - 2015	2PCBS3499 F C7	73 <u>5798</u> , 2PCBS3498 <i>F</i> C73 <u>5808</u> , 2PCBS3490 <u>F</u> C73 <u>5818</u>	
X3-45 VIP commercial use Model Year : 2015	From 2PCC	S349XFC73 <u>5748</u> up to 2PCCS3496FC73 <u>5911</u> incl. equipped with Bitzer A/C compressor	
XLII-45 Entertainer Model Year: 2013	2P	CYS3492 <u>D</u> C73 <u>5374</u> , 2PCYS3490 <u>D</u> C73 <u>5468</u>	
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.			

DESCRIPTION

On the vehicles affected by this bulletin, vibration is causing damage to A/C compressor and compressor harness connectors. Addition of a reinforcement bracket to Bitzer A/C compressor is needed to increase the installation stiffness and reduce vibration amplitude.



MATERIAL

Order WB15-19 which includes:

Part No.	Description	Qty
069206	HARNESS, A/C COMPRESSOR (1x)	1
062490	DOUBLE WALL SHRINK TUBE .250"125" / BLACK, 6" long	2
069356	DECAL	1
457675	REINFORCEMENT BRACKET, A/C COMPRESSOR	1
502949	SCREW, BUTTON HD HEX SOCKET M10 x 25lg SS [LINNIG CLUTCH]	1
504637	CABLE TIES, NYLON 3/16" x 13"	20
507664	CABLE TIE, NYLON 3/16" x 11" DOUBLE LOOP HEAD	5
509815	TREE MOUNT, FT	1
562228	BUTT SPLICE16-14 AWG	2
950576	COIL, UNLOADER ASSEMBLY	1
950577	O-RING, COMPRESSOR UNLOADER COIL	1
5001616	SOCKET HEAD CAP SCREW M10-1.5X25 LG [LANG CLUTCH]	2

Bulk material that may be required:

Part No.	Description	Qty	
950533	COIL, ELECTROMAGNETIC CLUTCH, [LANG CLUTCH]	1	
-	MOLYCOTE G-rapid-plus 400ml spray can [LANG CLUTCH]	20ml	
	(http://kravden.com/buy/dc-g-rapid-plus-400ml-spray-can.html)		

NOTE

Material can be obtained through regular channels.

TOOLS

Lang clutch extractor tool # 680888

REPAIR PROGRESS CHECKLIST

• M	IATERIAL
	MATERIAL REQUIRED IS IN STOCK
	OPTIONAL MATERIAL IS AVAILABLE
• R	EINFORCEMENT BRACKET INSTALLATION
	LANG CLUTCH INSPECTED AND REPLACED IF APPLICABLE
	SHAFT SEAL DRAIN TUBE REINSTALLED ON OPPOSITE SIDE
	REINFORCEMENT BRACKET INSTALLED
	BOLTS C & E TIGHTENED AS PER PRESCRIBED TORQUE
	WARNING DECAL AFFIXED
	CLUTCH COIL MOUNTING SCREWS TIGHTENED AS PER PRESCRIBED TORQUE
	ROTOR MOUNTING SCREW G TIGHTENED AS PER PRESCRIBED TORQUE
	BELT TENSION ADJUSTED
	BELT TENSIONER SCREW AND NUT PROPERLY TIGHTEN
• U	NLOADER COIL REPLACEMENT
	NEW CLIP-ON COIL INSTALLED
• Н	ARNESS #069206 INSTALLATION
	BRAND NEW HARNESS INSTALLATION NOT REQUIRED
or	
	BRAND NEW HARNESS INSTALLED AND PROPERLY SECURED
	CONNECTOR L199 SCREW TIGHTENED

CONNECTOR So9 REMOVED

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

REINFORCEMENT BRACKET INSTALLATION

- 1. Loosen bolt (A).
- 2. Unscrew and remove bolt (B).
- 3. Remove the drive belt tensioner.
- 4. Remove the drive belts. Note: Keep hardware for later use



- 5. Unscrew and remove bolt (C).
- 6. Discard block (**D**).

Note: Keep hardware for later use Make sure they are in good condition



LANG TYPE: SHARP EDGE COIL LINNIG TYPE: ROUND EDGE COIL 8. As an alternate way to confirm LANG Type clutch, locate "LANG" engraving on the hub center. Note for this type: Confirm you have two #5001616 socket head cap screws in your available material. These additional screws will be used to install the reinforcement bracket on the compressor. 9. If a LINNIG Type clutch is installed, refer to "LINNIG ELECTROMAGNETIC CLUTCH INSTALLATION / REMOVAL" at the end of this document.

7. AT THIS POINT, IDENTIFY THE TYPE OF CLUTCH INSTALLED ON YOUR VEHICLE.





- 11. Remove the existing shaft seal drain tube and support.
- 12. Reinstall on the opposite side as seen on the image on the right.

Note: Use existing hex socket head bolt and lock washer. Use blue Loctite 243 on threads.

 Install new reinforcement bracket #457675 as shown using previously removed hardware (bolt (C) and flat washer). <u>DO NOT tighten at</u> <u>this moment</u>.

Note: Use blue Loctite 243 on threads.



LANG clutches:

13.1. Carry on with the installation of new reinforcement bracket #457675 as shown. Use two "cylindrical head" socket cap screws #5001616 (E).

Tighten to 40 lbf-ft (43 N-m)



Note: Use blue Loctite 243 on threads.

LINNIG clutches only:

- *13.2.* Carry on with the installation of new reinforcement bracket **#457675** as shown.
- 13.3. Any standard bolt head would interfere with the coil body, therefore use two button head cap screws #502949 provided in the kit (E).

Tighten to 32 Ibf-ft (43 N-m)



Note: Use blue Loctite 243 on threads.

 14. Tighten bolt in location (C). C= 74 lbf-ft (100 N-m) Note: If bolts are difficult to drive in hole, the compressor may be moved. Loosen the compressor mounting bolts (4x) at the base. Tighten compressor mounting bolts to 74 lbf-ft. (100 N-m) 	
15. Reinstall tensioner, bolt and washer (B) and bolt and nut (A). You don't have to tighten these bolts as the belt tension adjustment will be done later in this procedure.	
16. Apply decal #069356 were indicated on the image.	DO NOT POWER WASH ALTERNATORS
17. Install nylon tie mount #509815 where indicated on the image.	

L

.

 Reinstall the electromagnetic clutch coil. Position cable lead on the right side. Slip the coil on the retainer on the compressor flange. Fasten the coil with 4 screws to the compressor.

Coil mounting screws (**F**): **22 lbf-ft** (30 N-m). *Use blue Loctite 243.*

Caution: Pay attention to the precise seat of the coil. A non-observance may cause the destruction of the clutch components during operation.

19. Mount the clutch on the shaft end.

The flange and the shaft end of the compressor must be free from dirt. Apply high temperature approved assembly grease on the shaft end for easy dismounting of the clutch.

Lang recommends the use of Molykote G-rapid-plus or Molykote P 40.

20. Carefully mount the rotor on the shaft end by hand.

Never use a hammer for pressing the rotor on.

To avoid damaging the bore of the rotor, feel the engagement of the key in the keyway and slip the rotor on the shaft end of the compressor till reaching the stop.

The Woodruff key on the shaft end and the groove in the location hole of the rotor must be flush.

21. Fasten the rotor to the shaft end by using the M12 screw and by holding-up with a wrench on the rotor.

Rotor mounting screw (**G**): **60 lbf-ft** (81 N-m) Use blue Loctite 243.

22. Turn rotor by hand and pay attention to the free run and the generation of noises. In case of grinding or similar noises, dismount the clutch and check installation.





23. Reinstall the drive belts.

On vehicles <u>not equipped</u> with an auxiliary alternator (i.e. 2 identical belts), belt tension should be within this range:

A belt strand tension gauge is needed 90-100 lbs <u>new</u> belts (mean of 2 belt values) 75-85 lbs <u>used</u> belts (mean of 2 belt values)

On vehicles equipped with an auxiliary alternator (i.e. 2 different belts), belt tension should be within this range:

A belt strand tension gauge is needed 150-160 lbs <u>new</u> belts (mean of 2 belt values) 120-130 lbs <u>used</u> belts (mean of 2 belt values)

Hand- tighten bolt (**B**) Apply loctite on bolt (**B**) Adjust belt tension using bolt (**A**). Use the jam nut to prevent rotation of bolt (**A**). When proper tension is achieved, tighten bolt (**B**) to **43 lbf-ft**. (58 N-m)



UNLOADER COIL REPLACEMENT

A new "clip-on" type unloader coil must be installed in order to avoid unloader failure.

- Loosen the screw securing the connector to the coil and then unplug the connector (A). Keep the screw and the connector rubber gasket for later use.
- 2. Unscrew the aluminum cap and discard.
- 3. Remove the plastic capture nut and discard.
- 4. Remove the coil and discard
- 5. Keep the O-ring on the stem.



- 6. Install the new clip-on coil on the stem.
- 7. Slide the coil over the stem assembly with the O-ring at the base of the stem.



HARNESS #069206 INSTALLATION

Skip the harness installation if a brand new harness has been installed recently while performing WB14-06.

If you're not installing a new harness, <u>DO NOT throw it away</u>. Keep it as spare part for later use if required.

1. While proceeding with one connector at a time, Se24 remove the existing A/C compressor harness simultaneously as you install the new harness. Se29 The new harness should be installed and routed like the one being removed. So9: A/C electromagnetic clutch Se29: A/C pressure switch L199: the R.H. side cylinder unloader coil Se23: high side pressure transducer C228 Se24: low side pressure transducer C228: other C228 connector half L199 Se23 Take special care to route the harness according to the following figures. Refer to best practices at the end of this document. Prefer larger, heat resistant cable ties over small cable ties to limit the "pinch effect". Secure the cable on the cable tie mounts where applicable.

- 2. Install new harness **069206.** Connect **L199** to the unloader coil. Tighten the screw securing connector L199 to the coil.
- 3. Secure the cable on the cable tie mounts.



Electromagnetic clutch connector So9. The clutch should be connected directly (hard wired) to the harness without using So9.

- 4. Write down wire color matching then cut the clutch connectors **So9** on harness and compressor.
- 5. Slip shrink tube #062490 over each wire. Slip an additional shrink tube over cable insulation.
- 6. Refer to table below if required to match wire colours. (According to VIN of vehicle).

	Clutch side		Harness side
Up to E-5698 /	Blue	→	White
E-2648 Excluded	Brown	→	Orange
From E-5698 / E-2648 And up	Red	→	Orange
	Green	→	Black

- According to table, splice wires with butt slice #562228. <u>Crimp and solder</u>. Inspect to make sure you have a good crimp and solder.
- 8. Seal each wire with shrink tube. Seal over the two wires and cable isolation with shrink tube.
- 9. Attach clutch cable along bracket as shown.







ATTACH THE EXCESS LENGTH OF CABLE ALONG MAIN STRAND OF HARNESS AS SHOWN- NYLON TIES LOCATION SHOWN BY ARROWS









LINNIG ELECTROMAGNETIC CLUTCH INSTALLATION/REMOVAL

PARTS / WASTE DISPOSAL

All replaced parts must be returned to Prevost according to the Return Shipping Instructions available on <u>https://www.prevostcar.com/content/warranty-documents</u> for full reimbursement. A copy of the warranty claim form must be enclosed with the shipment.

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and 2 hours (2.0h) of labor plus an additional half hour (0.5h) applicable only for the replacement of the *Lang clutch coil* by **#950533**, upon receipt of the replaced part and a warranty claim. Please submit claim via our Online Warranty System, available at <u>www.prevostcar.com</u> (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB15-19".

OTHER

VBC Bulletin	N/A
Fail Code	22.00
Defect Code	09
Syst. Cond	В
Causal Part	950002

Access all our Service Bulletins on

https://secureus5.volvo.com/technicalpublications/en/pub.asp or scan the QR-Code with your smart phone.

E-mail us at **technicalpublications_prev@volvo.com** and type "ADD" in the subject to receive our warranty bulletins by e-mail.

