

SAFETY RECALL

SR20-87

Date	Expiration	Group	No.	Page
11.2020	NA	36	5888	1(2)

First Release

11-06-2020

ENGINE STOP BUTTON IN ENGINE COMPARTMENT DOES NOT WORK
9700 (B13R)

MODEL YEAR(S) AND VEHICLE SERIAL NUMBERS (VIN) INVOLVED

NOTICE TO SERVICE CENTERS <i>Verify vehicle eligibility by checking recall status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevest website.</i>	
Model	VIN
Volvo 9700 us/can Model Year : 2020	The following individual vehicles: 3CET2V929L5 <u>198318</u> , 3CET2W429L5 <u>201926</u> , 3CET2W420L5 <u>201927</u> , 3CET2W422L5 <u>201928</u> , 3CET2W424L5 <u>201929</u> , 3CET2W420L5 <u>201930</u> , 3CET2W422L5 <u>201931</u> , 3CET2W424L5 <u>201932</u> , 3CET2W426L5 <u>201933</u> , 3CET2W428L5 <u>201934</u> , 3CET2W42XL5 <u>201935</u>
This recall does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this recall will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION

The activation of the start disability switch in the engine compartment for servicing the vehicle may not disable the possibility to start the engine from the driver's seat.

Prevest requires that all vehicles concerned shall be recalled, inspected and rectified immediately by connecting and uploading new engine software.

MATERIAL

No parts are required for this bulletin

SAFETY RECALL

SR20-87

Date	Expiration	Group	No.	Page
11.2020	NA	36	5888	2(2)

PROCEDURE

DANGER

Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

- 1) Connect Tech Tool and update EMS software, Node 1.1.0.

Note: The latest Tech Tool version should be installed or at least version 2.7.75 or higher.

Note: Pull the fuses for MCM (A36), see TSB B-08-22.

PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevest's normal warranty. We will reimburse you the parts and 0.4 hour(s) (24min) of labor upon receipt of a completed A.F.A. Please submit claim via our Online Warranty System, available at www.prevestcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Safety Recall SR20-87".

OTHER

VBC Bulletin	C5888
Fail Code	06.27-2
Defect Code	49
Syst.Cond.	R
Causal Part	70329277

Access all our Service Bulletins on <http://prevostparts.volvo.com/technicalpublications/en/pul.asp> or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive our warranty bulletins by e-mail.



Prevest engages in a continuous program of testing and evaluating to provide the best possible product. Volvo Bus, however, is not committed to, or liable for updating existing products.