



# WARRANTY BULLETIN

WB23-25

DATE: October 2023 SECTION: 18 BODY

EXPIRATION: October 2025

SUBJECT: QR CODE REPLACMENT

First Release 10-04-2023

# **APPLICATION**

# NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

Model	VIN	PREVOST CAR INC.
H3-45 coaches Model Year: 2024	From 2	PCH3349XRC72 <u>1453</u> up to 2PCH33498RC72 <u>1502</u> incl.

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

#### **DESCRIPTION**

On the vehicles affected by this bulletin, replace driver's and passenger's QR code.

#### **MATERIAL**

Order kit #WB23-25 includes the following parts:

Part No.	Description	Qty
406927	DECAL, QR CODE DRIVER	1
406926	DECAL, QR CODE PASSENGER	28

Other parts that may be required:

Part No.	Description	Qty
685840	GLASS CLEANER	1

NOTE	
Material can be obtained through regular channels.	

Writer: JPHD <QF7720952 Rev 9>

### **SAFETY PRECAUTIONS**

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



#### **PROCEDURE**





# **DANGER**

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

Writer: JPHD <QF7720952 Rev 9>





Writer: JPHD <QF7720952\_Rev 9>

# **PARTS / WASTE DISPOSAL**

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

# **WARRANTY**

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and one hour(s) (1.0) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at <a href="https://www.prevostcar.com">www.prevostcar.com</a> (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB23-25".

#### **OTHER**

VBC Bulletin	N/A
Fail Code	18.02
Defect Code	09
Syst. Cond	В
Causal Part	406926

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications\_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.

Writer: JPHD <QF7720952 Rev 9>