

PREVOST

WARRANTY BULLETIN

WB23-33

DATE :	February 2024	SECTION :	18 BODY
EXPIRATION:	February 2026		
SUBJECT :	INSTALLATION 100th ANNIVERSARY LOGO		

First Release

02-08-2024

APPLICATION

NOTICE TO SERVICE CENTERS	
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN 
H3-45 VIP motorhomes Model Year: 2022	2PCVS3498NC721211 2PCV33490NC721247 2PCVS3491NC721258 2PCVS349XNC721274 2PCVS3491NC721308
H3-45 VIP motorhomes Model Year: 2023	From 2PCVS3499PC721348 up to 2PCVS349XPC721505 incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION

On the vehicles affected by this bulletin add the 100th anniversary logo.

MATERIAL

Order kit #WB23-33 includes the following parts:

Part No	Description	Qty
492176	LOGO 100th ANNIVERSARY 	2

NOTE
<i>Material can be obtained through regular channels.</i>

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



Safety First!



PROCEDURE




DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.


Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

REAR ENGINE DOOR LOGO INSTALLATION



1. Locate the middle left of the rear engine door.



2. Clean the surface with alcohol.




3. Install the new logo 492176 in the indicated position.




RIGHT FRONT FENDER LOGO INSTALLATION


1. Locate top right of the right fender.



2. Clean the surface with alcohol.



3. Install the new logo 492176 in the indicated position under the logo H3-45.



PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevo's normal warranty. We will reimburse you the parts and ½ hour (0.5) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevo.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB23-33".

OTHER

VBC Bulletin	N/A
Fail Code	18.02
Defect Code	09
Syst. Cond	B
Causal Part	492176

Access all our Service Bulletins on
<http://techpub.prevo.com/en/>
or scan the QR-Code with your smart phone.



Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.