

First Release

06-10-2019

OBD & ELD DECALS INSPECTION
9700 (B13R)

MODEL YEAR(S) AND VEHICLE SERIAL NUMBERS (VIN) INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
Volvo 9700 us/can Model Year : 2018	Vehicles: 3CET2V920J5190069, 3CET2V927J5190070, 3CET2V929J5190071, 3CET2V920J5190072, 3CET2V922J5190073, 3CET2V924J5190074, 3CET2V926J5190075, 3CET2V923J5190079, 3CET2V92XJ5190080
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION


On the vehicles affected by this bulletin, an inspection must be performed to ensure that the OBD and ELD warning decals are applied at their respective location inside the vehicles. If one or both decal(s) are missing, they must be ordered and applied following the instructions below.

MATERIAL

Order the following parts as required:

Part No.	Description	Qty
23338070	OBD Warning Decal	1
390038	ELD Warning Decal	1

PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.
Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.


1. OBD warning decal inspection.

- Make sure that the OBD warning decal is present on the lower part of the dashboard (driver's side). See picture for correct location.
- If the decal is missing, order decal # **23338070** and apply it at the shown location on the dashboard.



2. ELD warning decal inspection.

- Make sure that the ELD warning decal is present in the front electrical compartment (stairway compartment). See picture for correct location.
- If the decal is missing, order decal # **390038** and apply it in the front electrical compartment as shown in the pictures.



WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and 1/2 hour (0.50) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB19-85".

OTHER

VBC Bulletin	N/A
Fail Code	18.08
Defect Code	09
Syst. Cond	B
Causal Part	390038

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>

or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive our warranty bulletins by e-mail.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Volvo Bus, however, is not committed to, or liable for updating existing products.