

PREVOST

WARRANTY BULLETIN

WB24-36

DATE: April 2025 SECTION: 01 ENGINE

EXPIRATION: April 2027

SUBJECT: SECONDARY ENGINE INFORMATION LABEL

REPLACEMENT

First Release 17-04-2025

APPLICATION

Verify vehicle eligibility by che	NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.		
Model	VIN	VIA BERGISTAN INC. PREVOST CAR INC. In CAMP FORCE TITE OR CAMA	
H3-45 coaches Model Year: 2024	From 2P	CH33492 <u>P</u> C72 <u>1282</u> up to 2PCH33493 <u>R</u> C72 <u>1553</u> incl.	
H3-45 VIP motorhomes Model Year: 2023	From 2P	CVS3499 <u>P</u> C72 <u>1348</u> up to 2PCVS3495 <u>P</u> C72 <u>1492</u> incl.	

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, the secondary engine label has typing errors and needs to be replaced.

MATERIAL

Order kit WB24-36 which contains the following part. Note that this kit is VIN specific.

Description	Qty
"IMPORTANT ENGINE INFORMATION" LABEL "IMPORTANT ENGINE INFORMATION" LABEL """" """ """ """ """ """ """	1

Writer: AM < QF7720952 Rev 13>

WB24-36 Page 2/6

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

Writer: AM < QF7720952 Rev 13>


WB24-36 Page 3 / 6

SECONDARY ENGINE INFORMATION LABEL REPLACEMENT 1. Open the compressor compartment door. PREVOST 2. Lift the release lever to unlatch the engine compartment door. 3. Open the engine compartment door. PREVOST

Writer: AM <QF7720952_Rev 13>

WB24-36 Page 4 / 6

- 4. Locate the secondary "IMPORTANT ENGINE INFORMATION" label to be replaced.
- 5. Ensure that the engine serial number on the existing and new label is the same.




- 6. Use a scraper to entirely remove the existing secondary engine label.
- 7. Clean the surface with an adhesive remover.



8. Carefully affix the new secondary engine label at the same location.


IMPORTANT NOTE

Do not install the new label over the old one.



Writer: AM

WB24-36 Page 5/6



Writer: AM <QF7720952_Rev 13>

WB24-36 Page 6 / 6

PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and 1/2 hour (0.5) of labor upon receipt of a warranty claim. Please submit a claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section).

• Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB24-36".

OTHER

VBC Bulletin	N/A
Fail Code	1.00
Defect Code	09
Syst. Cond	В
Causal Part	012824P

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.





Writer: AM < QF7720952 Rev 13>