



PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001



**WARRANTY
BULLETIN**

Wb08-19

DATE : DECEMBER 2008	SECTION : 01 - Engine
EXPIRATION: DECEMBER 2010	
SUBJECT : VOLVO D13 ENGINE – AFTERTREATMENT FUEL INJECTOR (AFI) CONTINUOUS AIR PURGE SYSTEM (REF. SP258-008)	

APPLICATION

Model	VIN																																												
<p>H3-41, H3-45 Coaches</p> <p>Model Year : 2008 - 2009</p>	<p>The following vehicles</p>																																												
	<table border="0"> <tr> <td>2PCH33496<u>8</u>C71 0948</td> <td>2PCH33495<u>9</u>C71 1347</td> </tr> <tr> <td>2PCH33494<u>8</u>C71 0995</td> <td>2PCH33499<u>9</u>C71 1349</td> </tr> <tr> <td>2PCH33498<u>8</u>C71 1096</td> <td>2PCH33490<u>9</u>C71 1353</td> </tr> <tr> <td>2PCH33493<u>8</u>C71 1202</td> <td>2PCH33494<u>9</u>C71 1355</td> </tr> <tr> <td>2PCH33492<u>8</u>C71 1207</td> <td>2PCH33496<u>9</u>C71 1356</td> </tr> <tr> <td>2PCH33493<u>8</u>C71 1216</td> <td>2PCH33491<u>9</u>C71 1359</td> </tr> <tr> <td>2PCH33492<u>8</u>C71 1224</td> <td>2PCH3349X<u>9</u>C71 1361</td> </tr> <tr> <td>2PCH33491<u>8</u>C71 1232</td> <td>2PCH33493<u>9</u>C71 1363</td> </tr> <tr> <td>2PCH33492<u>8</u>C71 1241</td> <td>2PCH33495<u>9</u>C71 1364</td> </tr> <tr> <td>2PCH33497<u>8</u>C71 1249</td> <td>2PCH33499<u>9</u>C71 1366</td> </tr> <tr> <td>2PCH33494<u>8</u>C71 1256</td> <td>2PCH33490<u>9</u>C71 1367</td> </tr> <tr> <td>2PCH33491<u>8</u>C71 1263</td> <td>2PCH33494<u>9</u>C71 1369</td> </tr> <tr> <td>2PCH33492<u>8</u>C71 1272</td> <td>2PCH33490<u>9</u>C71 1370</td> </tr> <tr> <td>2PCH33499<u>8</u>C71 1303</td> <td>2PCH33498<u>9</u>C71 1374</td> </tr> <tr> <td>2PCH3349X<u>9</u>C71 1313</td> <td>2PCH3349X<u>9</u>C71 1375</td> </tr> <tr> <td>2PCH33490<u>9</u>C71 1322</td> <td>2PCH33495<u>9</u>C71 1378</td> </tr> <tr> <td>2PCH33496<u>9</u>C71 1325</td> <td>2PCH33497<u>9</u>C71 1379</td> </tr> <tr> <td>2PCH3349X<u>9</u>C71 1327</td> <td>2PCH33416<u>9</u>C71 1383</td> </tr> <tr> <td>2PCH33493<u>9</u>C71 1329</td> <td>2PCH33492<u>9</u>C71 1385</td> </tr> <tr> <td>2PCH33491<u>9</u>C71 1331</td> <td>2PCH33494<u>9</u>C71 1386</td> </tr> <tr> <td>2PCH33495<u>9</u>C71 1333</td> <td>2PCH33413<u>9</u>C71 1387</td> </tr> <tr> <td>2PCH33499<u>9</u>C71 1335</td> <td>2PCH3349X<u>9</u>C71 1389</td> </tr> </table>	2PCH33496 <u>8</u> C71 0948	2PCH33495 <u>9</u> C71 1347	2PCH33494 <u>8</u> C71 0995	2PCH33499 <u>9</u> C71 1349	2PCH33498 <u>8</u> C71 1096	2PCH33490 <u>9</u> C71 1353	2PCH33493 <u>8</u> C71 1202	2PCH33494 <u>9</u> C71 1355	2PCH33492 <u>8</u> C71 1207	2PCH33496 <u>9</u> C71 1356	2PCH33493 <u>8</u> C71 1216	2PCH33491 <u>9</u> C71 1359	2PCH33492 <u>8</u> C71 1224	2PCH3349X <u>9</u> C71 1361	2PCH33491 <u>8</u> C71 1232	2PCH33493 <u>9</u> C71 1363	2PCH33492 <u>8</u> C71 1241	2PCH33495 <u>9</u> C71 1364	2PCH33497 <u>8</u> C71 1249	2PCH33499 <u>9</u> C71 1366	2PCH33494 <u>8</u> C71 1256	2PCH33490 <u>9</u> C71 1367	2PCH33491 <u>8</u> C71 1263	2PCH33494 <u>9</u> C71 1369	2PCH33492 <u>8</u> C71 1272	2PCH33490 <u>9</u> C71 1370	2PCH33499 <u>8</u> C71 1303	2PCH33498 <u>9</u> C71 1374	2PCH3349X <u>9</u> C71 1313	2PCH3349X <u>9</u> C71 1375	2PCH33490 <u>9</u> C71 1322	2PCH33495 <u>9</u> C71 1378	2PCH33496 <u>9</u> C71 1325	2PCH33497 <u>9</u> C71 1379	2PCH3349X <u>9</u> C71 1327	2PCH33416 <u>9</u> C71 1383	2PCH33493 <u>9</u> C71 1329	2PCH33492 <u>9</u> C71 1385	2PCH33491 <u>9</u> C71 1331	2PCH33494 <u>9</u> C71 1386	2PCH33495 <u>9</u> C71 1333	2PCH33413 <u>9</u> C71 1387	2PCH33499 <u>9</u> C71 1335	2PCH3349X <u>9</u> C71 1389
	2PCH33496 <u>8</u> C71 0948	2PCH33495 <u>9</u> C71 1347																																											
	2PCH33494 <u>8</u> C71 0995	2PCH33499 <u>9</u> C71 1349																																											
	2PCH33498 <u>8</u> C71 1096	2PCH33490 <u>9</u> C71 1353																																											
	2PCH33493 <u>8</u> C71 1202	2PCH33494 <u>9</u> C71 1355																																											
	2PCH33492 <u>8</u> C71 1207	2PCH33496 <u>9</u> C71 1356																																											
	2PCH33493 <u>8</u> C71 1216	2PCH33491 <u>9</u> C71 1359																																											
	2PCH33492 <u>8</u> C71 1224	2PCH3349X <u>9</u> C71 1361																																											
	2PCH33491 <u>8</u> C71 1232	2PCH33493 <u>9</u> C71 1363																																											
	2PCH33492 <u>8</u> C71 1241	2PCH33495 <u>9</u> C71 1364																																											
	2PCH33497 <u>8</u> C71 1249	2PCH33499 <u>9</u> C71 1366																																											
	2PCH33494 <u>8</u> C71 1256	2PCH33490 <u>9</u> C71 1367																																											
	2PCH33491 <u>8</u> C71 1263	2PCH33494 <u>9</u> C71 1369																																											
	2PCH33492 <u>8</u> C71 1272	2PCH33490 <u>9</u> C71 1370																																											
	2PCH33499 <u>8</u> C71 1303	2PCH33498 <u>9</u> C71 1374																																											
	2PCH3349X <u>9</u> C71 1313	2PCH3349X <u>9</u> C71 1375																																											
	2PCH33490 <u>9</u> C71 1322	2PCH33495 <u>9</u> C71 1378																																											
	2PCH33496 <u>9</u> C71 1325	2PCH33497 <u>9</u> C71 1379																																											
	2PCH3349X <u>9</u> C71 1327	2PCH33416 <u>9</u> C71 1383																																											
2PCH33493 <u>9</u> C71 1329	2PCH33492 <u>9</u> C71 1385																																												
2PCH33491 <u>9</u> C71 1331	2PCH33494 <u>9</u> C71 1386																																												
2PCH33495 <u>9</u> C71 1333	2PCH33413 <u>9</u> C71 1387																																												
2PCH33499 <u>9</u> C71 1335	2PCH3349X <u>9</u> C71 1389																																												

	<p>2PCH33492<u>9C71 1337</u> 2PCH33496<u>9C71 1390</u> 2PCH33496<u>9C71 1339</u> 2PCH33498<u>9C71 1391</u> 2PCH33494<u>9C71 1341</u> 2PCH33497<u>9C71 1396</u> 2PCH33498<u>9C71 1343</u> 2PCH33495<u>9C71 1400</u> 2PCH33491<u>9C71 1345</u> 2PCH33499<u>9C71 1402</u></p>
<p>X3-45 Coaches Model Year : 2008 - 2009</p>	<p>The following vehicles 2PCG33490<u>8C72 9295</u> 2PCG33494<u>8C72 9364</u> 2PCG33496<u>9C72 9514</u> 2PCG33491<u>9C72 9520</u> 2PCG33491<u>9C72 9582</u> 2PCG33495<u>9C72 9584</u></p>
<p>This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</p>	

DESCRIPTION

On the vehicles affected by this bulletin, it is necessary to install an air pressure regulator and an air line connected to the AFI (the fuel injector fixed on the exhaust pipe for regeneration purposes) to purge the injector that might become clogged with exhaust gas soot. This modification is necessary in order to assure efficiency of the regeneration process.

You must make an appointment as soon as possible at one of Prevest Service Centers or Prevest Certified Service Providers. Please, contact your Prevest Regional Service Manager to find out the nearest service center location.

Prevest Action Service System (PASS) 1 800 463-7738

Regional Service Managers		
Sylvain St-Amant	Ontario, Quebec	1 888 634-5171
Jean Ruel	Quebec, New Brunswick, Newfoundland, Nova Scotia, Prince Edward Island, Maine	1 800 380-7738
Brian Godfroid	Washington State, British Columbia, Alberta, Saskatchewan, Manitoba	1 866 770-8892
Tommy Nolet	New York State, Connecticut, Massachusetts, Vermont, New Hampshire, Rhode Island	1 800 65-PREVO (77386)
Dave Langlois	Delaware, Maryland, Washington DC. Virginia, West Virginia, North Carolina, Pennsylvania, New Jersey, Ohio, Kentucky	1 866-95-PREVO (77386)
Kevin Laughlin	Missouri, Illinois, Minnesota, Wisconsin, Iowa, Tennessee, Kansas, Indiana, Michigan	1 800 38-PREVO (77386)
James Malcomb	Mississippi, Oklahoma, Texas, Louisiana, Arkansas, Alaska	1 800 83-PREVO (77386)
Tom Munds	Utah, Arizona, Colorado, New Mexico, Nebraska,	1 877 55-PREVO (77386)

	Idaho, Montana, North Dakota, South Dakota, Wyoming	
Fernando Martinez	California, Nevada, Oregon	1 800 95-PREVO (77386)
Bryan Joy	Florida, Georgia, Alabama, South-Carolina	1 866 61-PREVO (77386)
Bill Jensen	Hawaii, Motor Home and shell division	1 800 99-PREVO (77386)

PROCEDURE

Service technicians, for the complete procedure, refer to Service Program SP258-008 on IMPACT.

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and four hours (4.0) of labor upon receipt of the replaced parts and a completed A.F.A. form on which you must specify as per "Warranty Bulletin 08-19".

Parts / Waste disposal:

Return replaced parts to Prevost with A.F.A. for full reimbursement.
--