
Date	Expiration	Group	No.	Page
07.2010	07.2012	255	015	2(4)

DESCRIPTION

Wires within the smart remote actuator (SRA) connector located on the engine, below the turbocharger, are subject to vibration during engine operation. This vibration can result in terminal fretting which produces very fine dust particles, and can be seen as a fine green dust inside the connector. When these particles migrate between the female and male pin connections, intermittent contact problems may result and be made evident by SID 27 and PSID 232 fault codes. Installation of a back shell and securing of the SRA harness is necessary in order to prevent any dysfunction.

The following Volvo D13 engines are affected by this defect and must be corrected: From engine serial number 901653 up to 929271 included.

Please contact your Prevest Service Center or Authorized Service Provider for additional information and to schedule an appointment at your earliest convenience. Please mention Warranty Bulletin WB10-55. A complete list of the Prevest service points is available on www.prevestcar.com/network.

Prevest Action Service System (PASS) 1 800 463-7738

Date Expiration Group No. Page
07.2010 07.2012 255 015 3(4)

Regional Service Managers		
Brian Godfroid	Washington State, British Columbia, Alberta, Saskatchewan, Manitoba	1 866 770-8892
Tommy Nolet	New York State, Connecticut, Massachusetts, Vermont, New Hampshire, Rhode Island	1 800 65-PREVO (77386)
Dave Langlois	Delaware, Maryland, Washington DC, Virginia, West Virginia, North Carolina, Michigan, Pennsylvania, New Jersey, Ohio, Kentucky	1 866-95-PREVO (77386)
Kevin Laughlin	Missouri, Illinois, Minnesota, Wisconsin, Iowa, Tennessee, Kansas, Indiana,	1 800 38-PREVO (77386)
James Malcomb	Mississippi, Oklahoma, Texas, Louisiana, Arkansas, Alaska	1 800 83-PREVO (77386)
Tom Munds	Utah, Arizona, Colorado, New Mexico, Nebraska, Idaho, Montana, North Dakota, South Dakota, Wyoming	1 877 55-PREVO (77386)
Fernando Martinez	California, Nevada, Oregon	1 800 95-PREVO (77386)
Bryan Joy	Florida, Georgia, Alabama, South-Carolina	1 866 61-PREVO (77386)
Jean Ruel	Quebec, New Brunswick, Newfoundland, Nova Scotia, Prince Edward Island, Maine	1 800 380-7738
Sylvain St-Amant	Ontario, Quebec	1 888 634-5171
Bill Jensen	Hawaii, Motor Home and shell division	1 800 99-PREVO (77386)

Prevost Service Centers		
Quebec	850, chemin Olivier Saint-Nicolas, Quebec G7A 2N1	Toll free phone: 1-866-870-2046 Tel.: 1-418-831-2046
British Columbia	6537 River Road Delta, BC V4K 5B9	Tel.: 1-604-940-3306
New Jersey	201 South Avenue South Plainfield, New Jersey 07080	Toll free phone: 1-800-223-0830 Tel.: 1-908-222-7211
Florida	6931 Business Park Blvd. North Jacksonville, Florida 32256	Toll free phone: 1-800-874-7740 Tel.: 1-904-886-4555
Tennessee	800 South Cartwright Street Goodlettsville, Tennessee 37072	Toll free phone: 1-877-299-8881 Tel.: 1-615-299-8881
Texas	15200 Frye Road Fort Worth, Texas 76155-2702	Toll free phone: 1-866-773-8678 Tel.: 1-817-685-0250
California	3384 De Forest Circle Mira Loma, California 91752	Toll free phone: 1-800-421-9958 Tel.: 1-951-360-2550

Date	Expiration	Group	No.	Page
07.2010	07.2012	255	015	4(4)

Prevost Parts Customer Service		
US Prevost Parts Customer Service	2200 Point Blvd., Suite 100 Elgin, Illinois 60123	Toll free phone: 1-800-621-5519 Coach Tel.: 1-847-844-7680
Prevost Canadian Parts Customer Service	2955-A, avenue Watt Quebec, Quebec G1X 3W1	Toll free phone: 1-800-463-8876 Phone: 1-418-653-0948 Parts

PROCEDURE

Service technicians, for the complete procedure, refer to Volvo document **FSB255-015, Turbocharger Smart Remote Actuator (SRA) Faults** available on Impact.

ESTIMATED TIME

The estimated time required to perform this warranty bulletin is approximately 0.7 hours. As a matter of normal service process, your Prevost Service Center or Authorized Service Provider will also check for other repair measures which might be applicable to your vehicle and this may increase the required total service time.

WARRANTY

This modification is covered by Prevost's normal warranty and will be performed at no charge.

Please contact your Prevost Service Center or your Prevost Certified Service Providers for additional information and to schedule an appointment at your earliest convenience. Please mention WB10-55.

TELL US WHAT YOU THINK!

We are interested in hearing your comments or suggestions regarding this bulletin. Please e-mail them to: TechnicalPublications@volvo.com

Volvo Bus engages in a continuous program of testing and evaluating to provide the best possible product. Volvo Bus, however, is not committed to, or liable for updating existing products.