

PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

**WARRANTY
BULLETIN**

Wb99-17B




DATE : OCTOBER 1998	SECTION : 06 - Electrical
EXPIRATION: OCTOBER 1999	
SUBJECT : FASTENING THE C500 AND C506 CONNECTORS	

REVISION : B

VEHICLES X-2998, X-3021 AND X-3061 EXCLUDED FROM BULLETIN

APPLICATION

Model	VIN
H3-41 and H3-45 Coaches WITHOUT PRODRIVER OPTION Model Year : 1998 - 1999	 2PCH33494W1012234 AND From 2PCH3349XW1012285 up to 2PCH33493X1013070 incl. EXCEPT 2PCH33491X1012998 AND 2PCH33491X1013021
H3-45 VIP coach Shells WITHOUT PRODRIVER OPTION Model Year : 1998 - 1999	From 2PCV33497W1012294 up to 2PCV3349XX1013067 incl. EXCEPT 2PCV33499X1013061

DESCRIPTION

On vehicles without the Prodriver option, connector C500 must be fastened to a nearby wire harness to keep it off the floor and out of humidity and dirt. On vehicles without the digital clock, connector C506 connector must be fastened off the floor for the same reasons.

PROCEDURE

Warning : Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Open the front service compartment.
2. Locate connectors C500 and C506 (look to the upper right corner of the compartment).
3. If any or both connectors are not tied or connected to anything, coat with Nyogel, then attach to any nearby wire harness (using a cable tie), to keep off of the floor.

WARRANTY

This modification is covered by Prévost Car's normal warranty. We will reimburse one quarter of an hour (0.25) of labour upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 99-17B".