

MAINTENANCE INFORMATION

MI20-81

DATE :April 2020SECTION : 06ELECTRICALSUBJECT :AVOID WATER INFILTRATION IN MARKER LIGHTS

First Release

05-05-2020

IMPORTANT NOTICE

This modification is recommended by Prevost to increase your vehicle's performance. Note that no reimbursement will be awarded for carrying out this modification.

APPLICATION

Model	VIN	
Volvo 9700 Model Year : 2019 -2021		Before 3CET2V922L5200491.

DESCRIPTION

This maintenance information explains the correct installation of market lights, to avoid water infiltration on Volvo coaches.

MATERIAL

Order the following parts:

Part No.	Description	Qty
8714430	Adhesive Sealant, Sikaflex 221-Black	1*200
8714384	Aktivator 100, Adhesion Promoter	1*50

Order the following parts as required:

Part No.	Description	Location	Qty
20480486	Side Marking Lamp, With Reflex Reflector	Front	1
21277203	Lamp, Sidemarker DOT-Amber	Side Front	1
21277205	Lamp, Sidemarker DOT-Red	Side Rear	1
70364302	Side Marking Lamp, With Reflex Reflector	Rear	1

TOOLS:

Part No.	Description	Qty
9998081	Torque Wrench (0.6 N/m - 6 N/m)	1


PROCEDURE





DANGER

Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy..







PARTS / WASTE DISPOSAL

Discard according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)