



# PREVOST

## WARRANTY BULLETIN

**WB17-08**

DATE :	September 2017	SECTION :	23 ACCESSORIES
EXPIRATION:	September 2019		
SUBJECT :	<b>AFSS EXTINGUISHER HEAD SCREWS</b>		

### APPLICATION

<i>NOTICE TO SERVICE CENTERS</i>	
<i>Verify vehicle eligibility by checking warranty bulletin status with <b>SAP</b> or via <b>ONLINE WARRANTY SYSTEM</b> available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
H3-45 coaches Model Year : 2018	2PCH33494JC713935 2PCH33499JC713946
X3-45 VIP motorhomes Model Year : 2018	2PCCS3495JC736220 2PCBS3496JC736223 2PCCS349XJC736228
<p><b>This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</b></p>	

### DESCRIPTION

On the vehicles affected by this bulletin check tightening on both IFSS extinguisher head screws. If screws are loosened, tighten to the torque value specified below.

### MATERIAL

No parts are needed for this bulletin.

### PROCEDURE

DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button.

## SCREW TIGHTENING

1. Locate the AFSS extinguisher in the middle baggage compartment on the LH side of the vehicle.
2. Use a torque wrench and tighten the two extinguisher head screws shown on Figure 1 to the following torque value:

**TORQUE: 14 lb-ft (19 Nm)**

3. Bulletin is complete.



Figure 1

## PARTS / WASTE DISPOSAL

No parts disposal.

## WARRANTY

This modification is covered by Prevo's normal warranty. We will reimburse you half hour (30 min.) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at [www.prevo.com](http://www.prevo.com) (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB17-08".

## OTHER

VBC Bulletin	N/A
Fail Code	23.08
Defect Code	09
Syst. Cond	B
Causal Part	901125

Access all our Service Bulletins on  
<http://techpub.prevo.com/en/>  
or scan the QR-Code with your smart phone.



**Are you a Vehicle owner?** E-mail us at [technicalpublications\\_prev@volvo.com](mailto:technicalpublications_prev@volvo.com) and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.