



PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

MAINTENANCE INFORMATION Mi00-21



DATE : July 2000	SECTION : 18 - Body
SUBJECT : LATCH WITH GREASE FITTING FOR SERVICE COMPARTMENT DOORS	

Important Notice: This modification is recommended by Prévost Car to increase your vehicle's performance. Note that no reimbursement will be awarded for carrying out this modification.

APPLICATION

Model
XLII-45 Coach Model Year : 2000
XLII-45 Bus Shell Model Year : 2000

DESCRIPTION

A latch with grease fitting is available. This latch is installed on the engine compartment door, engine compartment R.H. side door, radiator door, L.H. and R.H. side rear service compartment door, evaporator and condenser compartment door and front service compartment door.

MATERIAL

Part No.	Description	Qty
780587	Latch with grease fitting, replaces latch #780282	1
780588	Latch with grease fitting, replaces latch #780283	1

Note : Material can be obtained through regular channels.

PROCEDURE

Warning : Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. With the use of the parts manual, identify the latch to determine the replacement latch.
2. Remove the latch. Transfer the latch lever to the new latch. Fix with pop rivet $\frac{3}{16}$ X $\frac{1}{4}$ (Prévost #504379).

Note : *If necessary, replace the lever by a new one. See the parts manual for the part number.*

3. Install the new latch.

Waste disposal :

Discard according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)