


**PREVOST**

**WARRANTY  
BULLETIN**

**WB14-39**

DATE :	SEPTEMBER 2014	SECTION :	22 - HVAC
EXPIRATION:	SEPTEMBER 2016		
SUBJECT :	POWER CABLE INSPECTION AND DECAL ADDITION		

**APPLICATION**

<i>NOTICE TO SERVICE CENTERS</i>	
<i>Verify vehicle eligibility by checking warranty bulletin status with <b>SAP</b> or via <b>ONLINE WARRANTY SYSTEM</b> available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
H3-41, H3-45 coaches Model Year : 2014, 2015	 Select vehicles within range: From 2PCH33494 <b>EC712662</b> up to 2PCH3349X <b>EC712702</b>
H3-45 VIP Shell Model Year : 2014	Single vehicle 2PCVS3494 <b>EC712666</b>
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

**DESCRIPTION**

On the vehicles affected by this bulletin inspect a power cable going to the condenser fan motor. After inspection, add a decal inside the A/C control box cover.

**MATERIAL**

Order the following parts:

Part No.	Description	Qty
069158	DECAL HVAC AC CTRL H3	1

<b>NOTE</b>
<i>Material can be obtained through regular channels.</i>


## PROCEDURE



### DANGER

Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Open the evaporator compartment door (road side). Remove the control box cover and the fan housing cover.




2. Inspect the power cable at location shown in picture.



3. Cut the cable tie on top of fan housing to create some play on the cable. Adjust to give proper clearance.



4. Clean cover with alcohol. Let dry.
5. Place label #069158 inside control box cover in this location. (arrow)
6. Re-assemble covers.



## PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

## WARRANTY

This modification is covered by Prevest's normal warranty. We will reimburse you the parts and thirty minutes (30 min) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at [www.prevestcar.com](http://www.prevestcar.com) (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB14-39".

## OTHER

VBC Bulletin	N/A
Fail Code	22.00
Defect Code	09
Syst.Cond.	B
Causal Part	069158

Access all our Service Bulletins on [www.prevestcar.com/techpub/bulletinsen](http://www.prevestcar.com/techpub/bulletinsen) or scan the QR-Code with your smart phone.

E-mail us at [technicalpublications\\_prev@volvo.com](mailto:technicalpublications_prev@volvo.com) and type "ADD" in the subject to receive our warranty bulletins by e-mail.

