

	RANTY LETIN	WB	514-44B
DATE :	SEPTEMBER 2014	SECTION :	06 - Electrical
EXPIRATION:	SEPTEMBER 2016	i	
SUBJECT :	VECU PARAMETE	RS CHANGE	
	Electrical Air Dryer Cut-Off Pressure & Desiccant Regeneration Factor		

 $\mathbf{E} \mathbf{V} \mathbf{O} \mathbf{S}$

- REVISION : THIS WARRANTY BULLETIN SUPERSEDES PREVIOUS VERSION.
 - B Warranty section modified. "We will reimburse you the parts and 3/4 hour..." changed for "We will reimburse you 3/4 hour..."
 - A Former Part 1 DPF Temp Sensors T1, T2, T3 Rationality Check removed from this bulletin. Vehicles Involved with former Part 1 update will be corrected on a subsequent bulletin.

DESCRIPTION

On the vehicles affected by this bulletin, changing of VECU (Vehicle Electronic Control Unit) parameters is necessary.

This update must be carried out by qualified technicians. Make an appointment with your nearest Prevost Service Center.

ELECTRIC AIR DRYER CUT-OFF PRESSURE & DESICCANT REGENERATION FACTOR

This update involves all **OBD13** & **GHG14** vehicles in service (refer to Application table for involved vehicles range).

This update will reduce air dryer cut-off pressure from 144 psi to 140 psi and extend desiccant regeneration time, thus preventing presence of water in the accessory tank.

APPLICATION – ELECTRIC AIR DRYER CUT-OFF PRESSURE & DESICCANT REGENERATION FACTOR

NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.			
Model			
H3-41, H3-45 coaches Model Year : 2013 - 2015	The following vehicles : 2PCH3349XDC71 <u>2146</u> 2PCVS349XDC71 <u>2248</u> 2PCH33494DC71 <u>2272</u>		
H3-45 VIP motorhomes Model Year : 2014 - 2015	And certain vehicles within the following range: From 2PCH33499DC71 <u>2364</u> up to 2PCH33498FC71 <u>2729</u> incl.		
X3-45 coaches Model Year : 2014 - 2015	The following vehicles : 2PCYS3492DC73 5374 2PCG33491DC73 5388 2PCG33492DC73 5433		
X3-45 VIP motorhomes And commercial use Model Year : 2014 - 2015	And certain vehicles within the following range: From 2PCG33497EC73 5459 up to 2PCC33492FC73 5773 incl.		
	ily apply to all the above-mentioned vehicles, some vehicles may have been modified the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle ch vehicle concerned.		

PROCEDURE



Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

- 1. Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector (OBD). Connect the PC to a functional LAN or modem connection and a 120 Volt AC source.
- 2. Turn the ignition switch "ON".
- 3. Once the vehicle has been identified and selected, perform Campaign S6991.

WARRANTY

This software update is covered by Prevost's normal warranty. We will reimburse you 3/4 hour (0.75) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at <u>www.prevostcar.com</u> (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB14-44".

OTHER

VBC Bulletin	S6991 (Part 2)	
Fail Code	06.27-1	
Defect Code	49	
Syst.Cond.	В	
Causal Part	3092091	

Access all our Service Bulletins on https://secureus5.volvo.com/technicalpublications/ en/pub.asp

or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive our warranty bulletins by e-mail.

