

PREVOST

WARRANTY BULLETIN

WB16-29

DATE:	JUNE 2016	SECTION:	01 - Engine
EXPIRATION:	JUNE 2018		
SLIB IECT ·	EMS ACM SOFT	WARE LIPDATE	OBD13-GHG14

Release 1 June 09, 2016

APPLICATION

NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.			
Model	VIN TO THE TOTAL T		
H3-45 coaches Model Year : 2013-2015	The following individual vehicles: 2PCH33499 D C71 2364 , 2PCH33497 E C71 2476 , 2PCH3349X E C71 2648 , 2PCH33493 F C71 2749 , 2PCH33491 F C71 2751 , 2PCH33495 F C71 2753 , 2PCH33499 F C71 2755 , 2PCH33494 F C71 2758 , 2PCH33499 F C71 2786 , 2PCH33496 F C71 2793 , 2PCH33495 F C71 2798 , 2PCH33499 F C71 2805 , 2PCH33492 F C71 2807 , 2PCH33497 F C71 2818		
H3-45 VIP motorhomes Model Year : 2013-2015	The following individual vehicles: 2PCVS3499 D C71 2452 , 2PCVS3490 E C71 2468 , 2PCVS3496 E C71 2524 2PCVS3496 E C71 2555 , 2PCVS3498 E C71 2587 , 2PCVS3499 E C71 2680 2PCVS3495 E C71 2689 , 2PCVS3497 E C71 2691 , 2PCVS3490 F C71 2715 2PCVS3499 F C71 2728 , 2PCVS3493 F C71 2742 , 2PCVS349X F C71 2768 2PCVS3497 F C71 2792 , 2PCVS3492 F C71 2800 , 2PCVS3498 F C71 2820		
X3-45 coaches Model Year : 2013-2015	The following individual vehicles: 2PCG33492 <u>E</u> C73 <u>5465</u> , 2PCG33496 <u>E</u> C73 <u>5470</u> , 2PCG33498 <u>E</u> C73 <u>5471</u> 2PCG33493 <u>E</u> C73 <u>5474</u> , 2PCG33493 <u>E</u> C73 <u>5488</u> , 2PCG33495 <u>E</u> C73 <u>5508</u> 2PCG33491 <u>E</u> C73 <u>5604</u> , 2PCG33493 <u>E</u> C73 <u>5605</u> , 2PCG3349X <u>E</u> C73 <u>5617</u> 2PCG33493 <u>E</u> C73 <u>5619</u> , 2PCG33491 <u>E</u> C73 <u>5621</u> , 2PCG3349X <u>E</u> C73 <u>5696</u> 2PCG33491 <u>E</u> C73 <u>5747</u> , 2PCG33490 <u>E</u> C73 <u>5755</u> , 2PCG3349X <u>F</u> C73 <u>5781</u> 2PCG3349X <u>F</u> C73 <u>5795</u> , 2PCG33491 <u>F</u> C73 <u>5796</u>		
X3-45 VIP commercial use Model Year : 2014-2015	The following individual vehicles: 2PCCS3497 <u>E</u> C73 <u>5642</u> , 2PCC33495 <u>F</u> C73 <u>5766</u> , 2PCCS3496 <u>F</u> C73 <u>5777</u> 2PCCS3490 <u>F</u> C73 <u>5788</u> , 2PCCS3496 <u>F</u> C73 <u>5794</u> .		
X3-45 VIP motorhomes Model Year : 2014 - 2015	The following individual vehicles: 2PCBS3491 <u>E</u> C73 <u>5504</u> , 2PCBS3495 <u>E</u> C73 <u>5537</u> , 2PCBS3490 <u>F</u> C73 <u>5740</u> 2PCBS3495 <u>F</u> C73 <u>5779</u>		
Volvo 9700, MY 2014	Single vehicle: 3CET2V225 <u>E</u> 516 <u>6754</u>		

Redact: FL <QF7720952_Rev 8>

DESCRIPTION

On the vehicles affected by this bulletin, update EMS and ACM software to the latest version available. This update must be carried out by qualified technicians. As soon as possible, make an appointment with your nearest Prevost Service Center or contact your service manager to carry out the update.

MATERIAL

No material is required for this bulletin.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine.

- 1. Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector (OBD). Connect the PC to a functional LAN or WiFi connection and a power source.
- 2. Turn the vehicle ignition switch to "ON".
- 3. Using PTT, update EMS and ACM software to the latest version available

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you thirty minutes(s) (30min) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB16-29".

OTHER

VBC Bulletin	TBC	
Fail Code	01.00-2	
Defect Code	49	
Syst. Cond	В	
Causal Part	3092091	

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone. E-mail us at **technicalpublications_prev@volvo.com** and type "ADD" in the subject to receive our warranty bulletins by e-mail.



Redact: FL < QF7720952_Rev 8>