

PREVOST

WB23-10B

BULLETIN

WARRANTY

DATE :April 2023SECTION :23 ACCESSORIESEXPIRATION:April 2025SUBJECT :CHANGE THE WCL BACK PLATE

Revision: B

Part disposal info modified: plate must be returned

04-27-2023

APPLICATION

Model	VIN	
		VEHICLES :
Model Year: 2023	2PCH3349XPC721 2PCH33495PC721 2PCH33490PC721	359 , 2PCH33499 P C72 1361 , 2PCH33490 P C72 1362 , 370 , 2PCH33491 P C72 1385 , 2PCH33493 P C72 1386 , 387 , 2PCH33499 P C72 1389 , 2PCH33495 P C72 1390 , 393 , 2PCH33492 P C72 1394 , 2PCH33498 P C72 1397 , 398 , 2PCH32402 P C72 1398 , 2PCH33498 P C72 1397 ,
	2PCH3349XPC721 2PCH33495PC721 2PCH33491PC721 2PCH33490PC721 2PCH33490PC721	398, 2PCH3349XPC721398, 2PCH3349XPC721398, 398, 2PCH33496PC721401, 2PCH33493PC721405, 406, 2PCH33494PC721414, 2PCH3349XPC721417, 421, 2PCH33493PC721422, 2PCH33499PC721425, 426, 2PCH33496PC721429, 2PCH33496PC721432, 433, 2PCH33496PC721434, 2PCH33495PC721437, 441, 2PCH33499PC721442.

DESCRIPTION

On the vehicles affected by this bulletin, verify the WCL back plate, if it is not the correct one, order 863104 and replace it.

MATERIAL

Order the following KIT: WB23-10 which contain:

Part No.	Description	Qty
863104	KIT, PLATE, BRIDGEPLATE	1

NOTE	
Material can be obtained through regular channels.	

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:




PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.



PARTS / WASTE DISPOSAL

All replaced parts must be returned to Prevost according to the Return Shipping Instructions available on <u>https://www.prevostcar.com/content/warranty-documents</u> for full reimbursement. A copy of the warranty claim form must be enclosed with the shipment.

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and 30 Minutes (.5 hour) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB23-10B ".

OTHER

VBC Bulletin	N/A
Fail Code	25.00
Defect Code	09
Syst. Cond	В
Causal Part	863104

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.

Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.

