

PREVOST

WARRANTY BULLETIN

WB23-40

DATE: January 2024 SECTION: 06 ELECTRICAL

EXPIRATION: January 2026

SUBJECT: **JUMPER ON CONNECTOR A175**

First Release 01-17-2024

APPLICATION

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.

Model	VIN			
H3-45 coaches Model Year: 2019 - 2023	From 2PCH33497KC720539 up to 2PCH3349XPC721272 incl.			
X3-45 coaches Model Year: 2019 - 2022	From 2PCG3349XKC736410 up to 2PCG33492NC736695 incl.			
X3-45 coaches Model Year: 2019 - 2020	From 4RKG33497 <u>K</u> 973 <u>7655</u> up to 4RKG33492 <u>L</u> 973 <u>7743</u> incl.			

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin add a jumper on connector A175.

MATERIAL

Order kit **WB23-40** which contains the following parts:

Part No.	Description	Qty
0610187	Jumper Connector, Boost Regulator	1

NOTE	
Material can be obtained through regular channels	

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:




PROCEDURE




DANGER

Park vehicle safely, apply parking brake, stop the engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On the Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lockout & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.





5. Connect jumper connector 0610187 to the harness, connector A175.

6. Confirm proper operation of the alternators.

PARTS / WASTE DISPOSAL

DO NOT RETURN THE REPLACED PARTS. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you the parts and $\frac{1}{2}$ hour (0.5) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB23-40".

OTHER

VBC Bulletin	N/A
Fail Code	06.20
Defect Code	09
Syst. Cond	В
Causal Part	560629

Access all our Service Bulletins on http://techpub.prevostcar.com/en/ or scan the QR-Code with your smart phone.

Are you a Vehicle owner? E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to receive warranty bulletins applicable to your vehicle(s) by e-mail.

