



ENREGISTRÉ-REGISTERED





PREVOST

DATE: MARCH 2000	SECTION: 23 - Accessories		
EXPIRATION: MARCH 2001			
SUBJECT : WINDSHIELD WASHER RESERVOIR			

APPLICATION

Model	VIN 📕	
XLII Bus shells Model Year: 2000	2PCW33499Y1027046 2PCW33490Y1027047 2PCW33492Y1027048 2PCW33494Y1027049 2PCW33490Y1027050 2PCW33492Y1027051 2PCW33494Y1027052 2PCW33496Y1027053 2PCW33496Y1027054 2PCW33493Y1027056 2PCW33493Y1027060 2PCW33493Y1027062 2PCW33499Y1027063 2PCW33490Y1027064 2PCW33490Y1027066 2PCW33496Y1027070 2PCW33496Y1027070 2PCW33498Y1027071 2PCW33498Y1027072 2PCW33491Y1027073 2PCW33493Y1027074 2PCW33495Y1027075	2PCW33497Y1027076 2PCW33499Y1027077 2PCW33490Y1027078 2PCW33490Y1027081 2PCW33492Y1027082 2PCW33494Y1027083 2PCW33496Y1027084 2PCW33496Y1027085 2PCW33493Y1027088 2PCX33493Y1027089 2PCW33491Y1027090 2PCW33497Y1027093 2PCW33499Y1027094 2PCW33496Y1027098 2PCW33490Y1027100 2PCW33492Y1027101 2PCY33497Y1027104 2PCW33493Y1027105 2PCY33490Y1027106 2PCW33495Y1027111 2PCW33495Y1027113 2PCW33492Y1027132
XLII Coaches Model Year: 2000	2PCX33491Y1027031	2PCX33490Y1027117

DESCRIPTION

A second rubber strap must be added to hold the windshield washer reservoir firmly in place.

MATERIAL

Part No.	Description	Qty
504694	Rubber strap	1

Note : Material can be obtained through regular channels.

PROCEDURE

Warning: Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

- 1. Open the front service compartment;
- 2. Install the original and the new rubber straps as shown on the figure below;
- 3. Close the front service compartment.




FIGURE 1: USE OF TWO STRAPS CROSSED OVER THE WINDSHIELD WASHER FLUID RESERVOIR

18381

WARRANTY

This modification is covered by Prévost Car's normal warranty. We will reimburse you the parts and one quater hour (0.25) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 00-04".