PREVOST

WARRANTY BULLETIN

Wb98-13A

ISO 9001
CERTIFIÉ·CERTIFIED
PREVOST

DATE : August 1998	SECTION : 12
SUBJECT : AD-9 AIR DRYER PURGE VALVE	

REVISION : A
Vehicle 2PCH33499W1012309 not concerned by this bulletin.

APPLICATION

Model	VIN
All H3 series vehicles equipped with Bendix AD-9 air dryer. Model Year: 1994 - 1998	2P9H33495R1001012, 2P9H33404R1001020, **AND** From 2P9V33494S1001057 up to 2PCH33498W1012446 incl. **EXCEPT** 2PCH33499W1012309
All XL series coaches **EXCEPT** XL coaches equipped with independant suspension Model Year: 1995 - 1998	2P9L33408S1001538, 2P9L33408S1001541, 2P9L33403S1001544, 2P9L33409S1001547, **AND** From 2P9L33409S1001550 up to 2PCL33498W1026552 incl.

DESCRIPTION :

In order to reduce air leakage from the existing purge valve on Bendix AD-9 equipped vehicles, a retrofit kit is now available.

MATERIAL

Part No.	Description	Qty
641464	AD-9 Purge Valve Assy. Replacement Kit	1

Note : *Material can be obtained through regular channels.*

PROCEDURE

Warning : *Park vehicle safely, apply parking brake, stop engine, set battery master switch(es) to the OFF position and drain wet tank to 0 p.s.i. (0 kPa) as per Maintenance Manual, section 12. Compressor discharge line may still contain residual pressure.*

1. Locate air dryer purge valve assembly on bottom of air dryer unit.

2. Replace purge valve assembly following installation instructions provided with the kit.

Note : *It is important to return the old assembly back to Prévost Car for refund .*

WARRANTY

This modification is covered by the manufacturer's normal warranty. We will reimburse you the parts and one quarter hour (0.25) of labor upon receipt of the old assy. and a completed A.F.A. form on which you must specify as per "Warranty Bulletin 98-13".

Parts disposition :

- Return to Prévost Car with A.F.A. for full reimbursement.

Expiration date : August 1999