



Windows ajar

Magnetic sensors window ajar LH



Window open = contact close
 Window close = contact open



Magnetic sensors window ajar RH

AE56

I/O_EA
24WUP

J2:1

0-Se4.1-20

C582:A

C601:1

C601:2

gnd-A56RJ1.18-18

C582:B

2.1_Gnd_Electro:5 C

C603:1

C603:2