

## Pneumatic diagram

### *PNEUMATIC DIAGRAMS H3-45 COACHES*

<b>NO:</b>	<b>D140407P0</b>	<b>REVISION :</b>	<b>J</b>
------------	------------------	-------------------	----------

<b>EFF. OC#</b>	N/A	<b>PRIOR TO OC#</b>	
<b>EFF. VEH#</b>	N/A	<b>PRIOR TO VEH#</b>	

<b>DR.</b>	R. Bouillon	<b>date</b>	2022-02-24
<b>CHK</b>	Pierre-Olivier Lachance	<b>appr</b>	Pierre-Olivier Lachance

REV.	DATE	DESCRIPTION	PAGE	BY	CHK.	APPR.
A	2013-07-16	Coach H3-45, New platform, rear sub-frame OC #2012125. Included OC #2012082 New Suspension Beam Axle. Preliminary Vehicles #E-2482 & #E-2495 Production Vehicle #E-2505 (Front beam axle suspension) D140407SP3 I-SHIFT Transmission Vehicle #E-2525	-	Rob.	M.J.H.	M.J.H.
B	2015-01-23	Coach H3-45, New front pneumatic unit & New air lines color code OC #2013172. Production Vehicle #F-2923	P.1,2,3,4,5, 6, SP1 & SP3	Rob.	M.J.H.	M.J.H.
C	2015-06-19	Add a muffler on the heater water valve who replaces 6mm OD tube exhaust. OC #2015028. #D140407P6 Update Revision C	P.1	Rob.	M.J.H.	M.J.H.
D	2017-09-29	Come back with exhaust tube 6 mm OD natural white color, On the heater water valve, remove muffler. OC #2015092. Production vehicle H3-45 #J-0042.	P.6 P.1	Rob. Rob.	M.J.H. M.J.H.	M.J.H. M.J.H.
E	2018-03-30	Add new TCM Allison module and R.E.L.S. Reduce Engine Load at Stop OC #2018011, Production vehicle #K-0370	P.5	Rob.	M.J.H.	M.J.H.
F	2019-09-23	Add new Special Customer option : Independante left and right luggage air door lock.	SP5	Rob.	P.O. LAC.	P.O. LAC
G	2020-03-06	SPECIAL Brown Coach: Front quick connect fitting air hose for towing, service compartment.	SP6	Rob.	P.O.LAC.	P.O.LAC.
H	2021-03-18	SPECIAL EL EXPRESO LLC TORNADO : Parking Brake Overrule	SP7	Rob.	P.O.LAC	P.O.LAC
I	2022-01-17	Diagram update, (FRONT AIR MANIFOLD BLOCK)	P.1	RGOS	P.O.LAC	P.O.LAC
J	2022-02-24	SPECIAL BREWSTER WITH RUD CHAIN TRACTION SYSTEM Vehicles : #P-1315, 16, 17, 20, 21	SP4	Rob.	P.O.LAC	P.O.LAC

