



PREVOST

MAINTENANCE INFORMATION

MI 97-36



DATE: February 1998	SECTION: 18
SUBJECT: SEDAN DOOR SYSTEM VALVE REPLACEMENT	

APPLICATION:

Model	VIN
H3 series coaches * Model Year: 1994 - 1998	 From 2P9H33495R1001012 up to 2PCH33499W1012388 incl.

DESCRIPTION

Sedan door opening system intensive use can run this system solenoid valves out of order. In these special cases, excessive prompting to the sedan door module solenoid coils can burn them out. The suggested kit cures this problem.

MATERIAL

Part No.	Description	Qty
285921	New manifold assembly with connections. (Instruction sheet included).	1

Note: Material can be obtained through regular channels.