



PREVOST

BULLETIN DE GARANTIE

Bg08-03

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001



DATE : Août 2008	SECTION : 12 - Freins
EXPIRATION : Août 2010	
SUJET : REPROGRAMMATION DU LOGICIEL DU DISPOSITIF ÉLECTRONIQUE DE STABILITÉ PROGRAMMÉ (ESP)	

APPLICATION

Modèle	VIN	
Autocars X3-45 Année modèle: 2008	2PCG334978C729259	
Autocars H3-45 Année modèle: 2008	2PCH3349581710855	
Carrosseries VIP-45 Année modèle: 2007	2PCV334937C710942 - 2PCV334907C710946 - 2PCV334927C710947 2PCV334927C710950 - 2PCV334987C710953 - 2PCV3349X7C710954 2PCV334957C710957 - 2PCV334907C710963 - 2PCV334967C710966 2PCV334917C710972 - 2PCV334957C710974 - 2PCV334927C710981 2PCV334967C710983 - 2PCV334987C710984 - 2PCV334937C710987 2PCV334997C710993 - 2PCV3349X7C710999 - 2PCV3349X7C711005	
Ce bulletin n'est pas nécessairement applicable à tous les véhicules ci-haut mentionnés, certains peuvent avoir été modifiés avant la livraison. Les propriétaires de véhicules visés par ce bulletin seront avisés par une lettre indiquant le numéro d'identification de chaque véhicule concerné.		

DESCRIPTION

Il a été porté à l'attention de Prevost que sur les véhicules ci-dessus mentionnés munis du système d'antidérapage automatique (ATC) et du dispositif électronique de stabilité programmé (ESP), il y a possibilité que le témoin lumineux ^(ATC) du tableau de bord reste allumé si les paramètres de «direction du mouvement» du capteur de la colonne de direction et du capteur d'accélération latérale n'ont pas été spécifiés dans la programmation.

Pour prévenir cette situation, nous vous recommandons fortement de prendre rendez-vous avec votre centre de service Prévost ou de contacter votre gérant régional de service afin de reprogrammer le logiciel du dispositif électronique de stabilité programmé (ESP).

Electronic Stability Program

File View Execute ?

Vehicle ID#: 8-9289 Search

Messages: RECOMMENDATION: Generate and Transfer the parameters!
Vehicle generic template has changed since last generation!
Parameter(s) have been added or deleted!

General | Vehicle Parameters | Generation | Transfer the Parameters | History

Next >>

Vehicle Info

VIN #: 2PCY3349X8C729289 Vehicle Type: MTH XI 2 45F
Sales Order: 0004041132 000010 Status: **In production**
Production Order: 000002116102 Production Date: 2007/08/21

Vehicle Events Data

	Current Data	Last Generation	Last Transfer
User name:	dese Eric Deshaies (LGS)	scelecpod (Electricien Production)	scelecpod (Electricien Production)
Date/hour:	2007/08/17 09:20:22	2007/08/16 09:21:24	2007/08/16 09:23:04
Parameters:	00089289 Rev:A01	00089289 Rev:A01	00089289 Rev:A01
Template/Date:	1400002 Rev:P02 2007-03-19	1400002 Rev:P01 2007-03-19	1400002 Rev:P01 2007-03-19

Bendix version WCP 1.1.9 ECU part # 5019416

User: dese Eric Deshaies (LGS) Profile: **Production** Network: On-Line ECU : Disconnect Last Update: 2007/08/17 09:18:23

Electronic Stability Program

File View Execute ?

Vehicle ID#: 8-9289 Search

Messages: RECOMMENDATION: Generate and Transfer the parameters!
Vehicle generic template has changed since last generation!
Parameter(s) have been added or deleted!

General | Vehicle Parameters | Generation | Transfer the Parameters | History

Compare parameter values between SAP Value and Current Value << Back Next >>

Vehicle Parameters

Para	Description	S	Default Value	SAP Value	Previous Value	Current Value	New Value
DEAXDM	DEF_AX_DEM_MIN		-3.0			-3.0	-3.0
DEDHML	DEF_DELTA_H_MAX_LEFT		21.0			21.0	21.0
DEDHMR	DEF_DELTA_H_MAX_RIGHT		-21.0			-21.0	-21.0
DEEGRE	DEF_EG_REF		0.0063			0.0063	0.0063
DEF1B0	DEF_ESP_FLAGS_1.BIT0	N	1				1
DEF1B1	DEF_ESP_FLAGS_1.BIT1		0			0	0
DEF1B2	DEF_ESP_FLAGS_1.BIT2	N	0				0
DEF1B3	DEF_ESP_FLAGS_1.BIT3		1			1	1
DEF1B5	DEF_ESP_FLAGS_1.BIT5		1			1	1
DEF2B3	DEF_ESP_FLAGS_2.BIT3		1			1	1
DEFIL0	DEF_IL_VALUES_0		22.3			22.3	22.3
DEFIL1	DEF_IL_VALUES_1		20			20	20
DEFIL2	DEF_IL_VALUES_2		21.8			21.8	21.8
DEFIL3	DEF_IL_VALUES_3		22.8			22.8	22.8
DEFILV	DEF_IL		20.8			20.8	20.8
DEGETY	DEF_GEARBOX_TYPE		2			2	2
DETREF	DEF_T_REF		0.340			0.340	0.340
DEVETY	DEF_ESP_VEHICLE_TYPE		22			22	22

User: dese Eric Deshaies (LGS) Profile: **Production** Network: On-Line ECU : Disconnect Last Update: 2007/08/17 09:18:23

The screenshot shows the 'Electronic Stability Program' software interface. At the top, there are three window titles. Below them is a menu bar with 'File', 'View', and 'Execute'. A toolbar contains various icons, including a yellow warning sign. A message box states: 'Messages: All compared parameters are identical!'. Below this is a search bar with 'Vehicle ID#: 8-9303' and a 'Search' button. The main area has tabs for 'General', 'Vehicle Parameters', 'Generation', 'Transfer the Parameters', and 'History'. The 'Generation' tab is active, showing a list of parameters. The last two rows are highlighted with a red box:

Parameter ID	Value	Unit	Parameter Name
P. 194:0x0044:B16:0	.1		DEF_ESP_FLAGS_1.BIT0
P. 194:0x0044:B16:2	.0		DEF_ESP_FLAGS_1.BIT2

At the bottom of the window, there is a status bar with the following information: 'User: dese Eric Deshaies (LGS)', 'Profile: Production', 'Network: On-Line', 'ECU : Disconnecter', and 'Last Update: 2007/08/17 09:18:23'.

GARANTIE

Cette modification est couverte par la garantie normale de Prévost. Nous vous rembourserons une heure (1,0) de main-d'œuvre sur réception d'un formulaire A.F.A. dûment complété sur lequel vous devez mentionner «Bulletin de Garantie 08-03».