

**PREVOST**ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

WARRANTY BULLETIN

Wb09-26

DATE: FEBRUARY 2010	SECTION: 01 - Engine
EXPIRATION: FEBRUARY 2012	
SUBJECT: ON VOLVO D13 ENGINES DASHBOARD "CHECK ENGINE" WARNING LAMP COULD COME ON DUE TO CODE PID 171	

APPLICATION

Model	VIN
H3-41, H3-45 Coaches Model Year : 2008 – 2009 - 2010	From 2PCH33496 <u>8C710948</u> up to 2PCH33497 <u>AC711564</u> incl.
X3-45 Coaches Model Year : 2008 – 2009 - 2010	From 2PCG33497 <u>8C729259</u> up to 2PCG33494 <u>AC729872</u> incl.
MTH XLII-45E Bus shells Model Year : 2009	2PCY33497 <u>9C729591</u> - 2PCY33496 <u>9C729596</u> - 2PCY33493 <u>9C729619</u> 2PCY3349X <u>9C729620</u> - 2PCY33493 <u>9C729622</u> - 2PCY33499 <u>9C729625</u> 2PCY33492 <u>9C729627</u> - 2PCY33496 <u>9C729629</u> - 2PCY33494 <u>9C729631</u> 2PCY33496 <u>9C729632</u> - 2PCY3349X <u>9C729634</u> - 2PCY33499 <u>9C729642</u> 2PCY33495 <u>9C729668</u> - 2PCY33490 <u>9C729738</u> - 2PCY33499 <u>9C729768</u>

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin and equipped with Volvo D13 engine, Engine Management System (EMS) software must be updated in order to reflect the latest modifications.

You must contact **Prevost Action Service System (PASS) 1 800 463-7738** in order to make an appointment as soon as possible at one of Prevost Service Centers or Prevost Certified Service Providers.

You may also contact your Prevost Regional Service Manager to find out the nearest service center location.

Regional Service Managers		
Sylvain St-Amant	Ontario, Quebec	1 888 634-5171
Jean Ruel	Quebec, New Brunswick, Newfoundland, Nova Scotia, Prince Edward Island, Maine	1 800 380-7738
Brian Godfroid	Washington State, British Columbia, Alberta, Saskatchewan, Manitoba	1 866 770-8892
Tommy Nolet	New York State, Connecticut, Massachusetts, Vermont, New Hampshire, Rhode Island	1 800 65-PREVO (77386)
Dave Langlois	Delaware, Maryland, Washington DC, Virginia, West Virginia, North Carolina, Pennsylvania, New Jersey, Ohio, Kentucky	1 866-95-PREVO (77386)
Kevin Laughlin	Missouri, Illinois, Minnesota, Wisconsin, Iowa, Tennessee, Kansas, Indiana, Michigan	1 800 38-PREVO (77386)
James Malcomb	Mississippi, Oklahoma, Texas, Louisiana, Arkansas, Alaska	1 800 83-PREVO (77386)
Tom Munds	Utah, Arizona, Colorado, New Mexico, Nebraska, Idaho, Montana, North Dakota, South Dakota, Wyoming	1 877 55-PREVO (77386)
Fernando Martinez	California, Nevada, Oregon	1 800 95-PREVO (77386)
Bryan Joy	Florida, Georgia, Alabama, South-Carolina	1 866 61-PREVO (77386)
Bill Jensen	Hawaii, Motor Home and shell division	1 800 99-PREVO (77386)

PROCEDURE

Using Premium Tech Tool (PTT), replace the complete Engine Management System (EMS) software.

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you one hour (1.0) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 09-26". Parts / Waste disposal:

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)
