

PREVOST



**WARRANTY
BULLETIN**

Wb97-18



DATE: October 1997	SECTION: 22
SUBJECT: FREON STICKERS REPLACEMENT	

APPLICATION:

Model	VIN		
H3-41 and H3-45 Vehicles Model Year: 1996 - 1997	<u>2PCH33492V1011901</u>	<u>2PCH33419V1011993</u>	<u>2PCH33497V1012064</u>
	<u>2PCH33494V1011910</u>	<u>2PCH33497V1012002</u>	<u>2PCH33494W1012086</u>
	<u>2PCH33498V1011912</u>	<u>2PCH33494V1012006</u>	<u>2PCH33492W1012121</u>
	<u>2PCH33490V1011919</u>	<u>2PCH3349XV1012009</u>	<u>2PCH33494W1012122</u>
	<u>2PCH33499V1011921</u>	<u>2PCH33496V1012010</u>	<u>2PCH33496W1012123</u>
	<u>2PCH33499V1011949</u>	<u>2PCH33498V1012011</u>	<u>2PCH33498W1012124</u>
	<u>2PCH3341XV1011954</u>	<u>2PCH33499V1012034</u>	<u>2PCH33497W1012132</u> <u>2PCH33418W1012134</u>

DESCRIPTION

On the above-mentioned vehicles equipped with Freon R-22 A/C system, freon sticker (Prévost # 453067) indicating the use of POE oil may have been affixed instead of freon sticker (Prévost # 453101) indicating the use of mineral oil.

Oil used in compressor is of the good type (mineral oil), **do not replace**. Only the sticker need to be replaced.

One sticker is located inside the engine compartment right hand side door and the other one is located in condenser compartment.

PROCEDURE

Warning: Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Replace freon sticker (Prévost # 453067) located inside engine compartment right hand side door with freon sticker (Prévost # 453101) (refer to fig. 1).

Caution: Do not use POE oil in Freon R-22 A/C System to avoid reducing compressor lifespan.




FIGURE 1: VEHICLE EXTERIOR

2. Replace freon sticker (Prévoist # 453067) located above receiver tank inside A/C condenser compartment with freon sticker (Prévoist # 453101) (refer to fig. 1 and 2).




FIGURE 2: CONDENSER COMPARTMENT

WARRANTY

This modification is covered by the manufacturer's normal warranty. Sticker is supplied with bulletin, we will reimburse you a quarter of an hour (0.25) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 97-18".

Expiration date: October 1998