



**MAINTENANCE
INFORMATION**

MI13-47

DATE :	AUGUST 2013	SECTION: 06-Electrical
SUBJECT :	CLOCK FAULT CODE SPN 251 FMI 10	

IMPORTANT NOTICE

This modification is recommended by PrevoSt to increase your vehicle's performance. Note that no reimbursement will be awarded for carrying out this modification.

APPLICATION

NOTICE TO SERVICE CENTERS

*Verify vehicle eligibility by checking warranty bulletin status with **SAP** or **Vehicle Warranty Information** tool found on PrevoSt–Systems tab of the Volvo Trucks Dealer Portal*

Model	VIN
H3 Coaches Model Year: 2011 - 2013	 2PCH33498AC711573, 2PCH33496AC711605, 2PCH33495AC711627, 2PCH33496AC711636, 2PCH33499BC711695 And from 2PCH33496BC711721 to 2PCH33491DC712276 incl.
H3 VIP Converted Coach Shells Model Year : 2011 - 2013	From 2PCVS3494BC711772 to 2PCVS3496DC712277 incl.
X3-45 Coaches Model Year: 2011 - 2013	2PCG33498AC729907, 2PCG33491AC729926, 2PCG33499BC729965, 2PCG33491BC729992 And from 2PCG33491BC735002 to 2PCG33492DC735383 incl.
X3-45 VIP Converted Coach Shells Model Year : 2012 - 2013	From 2PCBS3499CC735070 to 2PCBS3494DC735379 incl.
XL2-45 Entertainer Converted Coach Shells Model Year : 2011 - 2013	2PCYS3495BC729971 And from 2PCY33498BC735003 to 2PCYS3498DC735380 incl.

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

DESCRIPTION

On the vehicles affected by this bulletin, it is now possible to modify MID 128 modules showing clock fault code “**SPN 251 FMI 10**”.

To perform this modification, it is necessary to execute accessory kit **85136634** and reprogram the MID 140 module using Premium Tech Tool (PPT).

You can also contact your Prevest Service Center or Certified Service Provider to schedule an appointment and have this modification performed at your earliest convenience.

A complete list of all affiliated Prevest service points is available on www.prevestcar.com/network.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Identify the vehicle with PTT and run Accessory Kit 85136634 as shown below.



2. Order MID 140 program and perform required MID 140 programming.

Access all our Service Bulletins on
<http://prevostparts.volvo.com/technicalpublicatios/en/pub.asp>
Or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type "ADD" in the subject to
receive our warranty bulletins by e-mail.

