PREVOST

Warranty Bulletin

97-01

Date: January 1997

Section: 23

Subject: ERROR IN MODEL 1997 VEHICLE IDENTIFICATION NUMBER (VIN)

Application:

Model	VI.N. RP9L33407P1001649 PREVOST CAR INC. STECLARE OORCHESTER, QUE, CAMADA
All XL vehicle series Model Year: 1997	From 2PCL33490 <u>V</u> 102 <u>5988</u> up to 2PCM33495 <u>V</u> 102 <u>6141</u> incl.
All H3 vehicle series Model Year: 1997	From 2PCH33415 <u>V</u> 101 <u>1620</u> up to 2PCH33491 <u>V</u> 101 <u>1816</u> incl.

DESCRIPTION

Vehicle identification number (VIN) plates on above mentioned vehicles have been incorrectly stamped due to an unfortunate technical problem. VIN's on these vehicles do not comply with requirements of the US Federal Motor Vehicle Safety Standards and Regulations part 565 nor with FMVSS 115 of the Canadian Federal Motor Vehicle Safety Standards and Regulations. Indeed, the ninth digit which is the check digit, was attributed an incorrect value, therefore invalidating the entire number and the vehicle's registration. This bulletin is a **recall campaign**.

PROCEDURE

Warning: Park vehicle safely, apply parking brake, stop engine and set battery disconnect switch(es) to the OFF position prior to working on the vehicle.

1. Remove original plate (Fig. 1).

On H3 series vehicle, it is located near the left lower corner of windshield.


On XL series vehicle, it is located near the right lower corner of windshield.



FIGURE 1: LOCATION OF PLATE ON H3 AND XL VEHICLE SERIES

9701

2. Remove DOT Certification Label located on the L.H. side control panel in the driver's section (Fig. 2).



- Install new plate and new DOT Certification Label as previously.
- 4. Return original plate, original DOT Certification Label, recall certification sheet and A.F.A. form through registered mail to Martin Normand at Prévost Car Inc.

WARRANTY

This modification is covered by the manufacturer's normal warranty. We will reimburse you the parts and half an hour (0.5) of labor upon receipt a completed A.F.A. form on which you must specify as per "Warranty Bulletin 97-01".

PREVOST

Recall Certification Sheet

We hereby certify that Recall Instructions with regards to Warranty Bulletin # 97-01 have been performed on vehicle serial number:		
2 P	(Please complete)	
0	1	
Company name		
Mailing address		
Phone	Fax	
Signature:		
Date		
A.F.A. #		

Please return this completed document with your A.F.A. form.