Instruction Sheet

IS-22106

H3 LAVATORY FAN RETROFIT KIT

First Release

07-04-2023

MATERIAL

Kit #IS22106 includes the following parts:

Part No	Description	Qty
950707	BRUSHLESS FAN	1
455038	BRACKET LAVATORY FAN	1
455048	FAN GRILL	1
500539	NUT HEX NYRT NX500 M4-0.7	3
502556	WASHER FLAT SS 4.3X9X.8	3
500283	SCREW TC TR PH SS410 10-24X3/4	3
502653	SCREW MACHINE PAN PH SS M5-0.8X16	4

504324	CLAMP HOSE SS/CS 114-165	1
5001377	SCREW MACHINE PAN PH SS M5-0.8X8	4
5001137	WASHER FLAT SS .203X.438X.06	4
354192	INSULATION	1
IS-22106	INSTRUCTION SHEET	1
FI-22106	FEUILLE D'INSTRUCTION	1

Other parts that may be required:

Part No.	Description	Qty
680038	LOCTITE 243 50 ML.	1

NOTE

Material can be obtained through regular channels.

SAFETY PRECAUTIONS

- Eye protection should always be worn when working in a shop.
- Rules for Personal Protection Equipment should always be respected. Wear your PPE including but not limited to the following:



PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.





6. With MCC only, install the new foam 354192. It is self-adhesive.	
7. Install the hose on the fan assembly bracket using clamp 504324.	
8. With MCC only, drill holes 4mm(5/32) using fan bracket holes as a template.	4.4mm





PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)