



# H3-45 VIP



REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
00	2010-11-01	2010001	B-1772	First release	ALL	E.O	E.O	C.L
01	2010-11-17	2010039	B-1786	Relocate YAW sensor in front wheels	C1,C3, 1.1, 16.2	E.L.	E.L.	C.L.
02	2011-02-16	n/a	- - -	minor change on gateway ground	0, 38.1	MP	MP	C.L.
03	2011-07-18	2011015 2010119	C-1949 C-1949	Replace Power relays 70 Amp Electrical Driver's Seat General Update	0, C1, K, 3.3 L, 30.3 B1, B2, B3, G, 2.1, 5.1, 14.2, 18.2	E.L.	E.L.	C.L.
04	2011-09-14	2011003	C-2007	Replace MasterID and CECM by MCM	7.1	SD	DG	DG
05	2011-11-21	2011057 2011107 n/a	C-2047 Same Same	Volvo Link - TGW Gnd & Pwr of ACM General Update	37.1 3.1, 3.2, 3.3, 4.1, 5.1, 6.1, 7.1, 14.1, 14.5 A, B1, B2, B3, C1, 2.1	P.G. S.BEL. E.L.	D.G.	C.L
06	21-03-2012	2012020		<b>2012_R1</b> ESP STD, WIRES NETWORK	A, 2.1, 3.1, 4.1, 5.1, 6.1, 7.1, 8.1, 10.1, 13.1, 14.1, 14.2, 14.5, 15.1, 16.1, 38.1, 39.1, 0, C1, C3, E.	S.B	C.L	C.L
07	2012-07-20	2012097		Reverse Mo26 front door lock	0, 29.1	M.P.	C.L.	C.L.
08	2014-05-12	NA		Pages Update	0, 3.2	S.B.	C.L.	C.L.