



PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

MAINTENANCE INFORMATION Mi99-26



DATE : September 1999	SECTION : 23
SUBJECT : NEW SUMP TANK (H3) AND AUXILIARY SUMP TANK (XL-45)	

Important Notice: This modification is recommended by Prévost Car to increase your vehicle's performance. Note that no reimbursement will be awarded for carrying out this modification.

APPLICATION

Model	VIN
H3-41 & H3-45 Coaches Model Year : 1996 - 2000	From 2CH33493T1011572 up to 2PCH33493Y1013457 incl.
XL-45 Coaches Model Year : 1996 - 2000	From 2PCM33499T1025930 up to 2PCL33493Y1027045 incl.

DESCRIPTION

A new sump tank (H3) and a new auxiliary sump tank (XL-45) are available. These tanks are reinforced around the filling cap to prevent deformation and resulting problems.

MATERIAL

For **H3 series** vehicles, order the following parts :

Part No	Description	Qty
404862	Sump tank	1
404337	Heating coil (required only for sump tank with heating system option)	1
5011027	FP nut #10 (required only for sump tank with heating system option)	2
5011028	FP ferrule #10 (required only for sump tank with heating system option)	2
IS-99004	Instruction Sheet	1
FI-99004	Feuille d'instructions	1

For **XL-45 series** vehicles, order the following parts :

Part No	Description	Qty
404872	Auxiliary sump tank	1
404337	Heating coil (required only for auxiliary sump tank with heating system option)	1
5011027	FP nut #10 (required only for auxiliary sump tank with heating system option)	2
5011028	FP ferrule #10 (required only for auxiliary sump tank with heating system option)	2
IS-99004	Instruction Sheet	1
FI-99004	Feuille d'instructions	1

Note : Material can be obtained through regular channels.