

Date	Expiration	Group	No.	Page
07.2010	07.2012	237	014	1(3)

VOLVO D13 ENGINE – OIL SEEPAGE AT UNIT INJECTOR HARNESS
 PASS THROUGH FITTING
 (Ref.: FSB 237-014)
 9700 (B13R)

VEHICLES' SERIAL NUMBERS INVOLVED

VIN			
	2009	2009	2010
Volvo 9700 Model Year: 2009 - 2010	3CET2M62795127142	3CET2M62895133287	3CET2M626A5135799
	3CET2M62995127143	3CET2M62X95133288	3CET2M629A5135800
	3CET2M62095127144	3CET2M62195133289	3CET2M620A5135801
	3CET2M62095127371	3CET2M62895133290	3CET2M622A5135802
	3CET2M62295127372	3CET2M62X95133291	3CET2M624A5135803
	3CET2M62495127521	3CET2M62195133292	3CET2M626A5135804
	3CET2M62995129166	3CET2M62395133293	3CET2M628A5135805
	3CET2M62095129167	3CET2M62595133294	3CET2S220A5135856
	3CET2M62395131527	3CET2M62795133295	3CET2M62XA5136017
	3CET2M62495132072	3CET2M62995133296	3CET2M621A5136018
	3CET2M62695132073	3CET2M62295133513	3CET2M623A5136019
	3CET2M62895132074	3CET2M62495133514	3CET2M62XA5136020
	3CET2M62X95132075	3CET2M62695133515	3CET2M621A5136021
	3CET2M62195132076	3CET2M62895133516	3CET2M62XA5136129
	3CET2M62395132077	3CET2M62X95133517	3CET2M626A5136130
	3CET2M62795132857	3CET2M62195133518	3CET2M628A5136131
	3CET2M62995132858	3CET2M62795133880	3CET2M625A5136376
	3CET2M62095132859	3CET2M62995133881	3CET2M627A5136377
	3CET2M62795132860	3CET2M62095133882	3CET2M629A5136378
	3CET2M62995132861	3CET2M62295133883	3CET2M620A5136379
	3CET2M62095132862	3CET2M62495133884	3CET2M627A5136380
	3CET2M62295132863	3CET2M62695133885	3CET2M624A5136384
	3CET2M62495133173	3CET2M62295133964	3CET2M62XA5136390
	3CET2M62695133174	3CET2M62495133965	3CET2M621A5136391
	3CET2M62895133175	3CET2M62695133966	3CET2M623A5136392
	3CET2M62X95133176	3CET2M62695134115	3CET2M625A5136393
			3CET2M627A5136394
			3CET2M629A5136395
			3CET2M620A5136396
			3CET2M622A5136397
			3CET2M624A5136398
			3CET2M626A5136399
		3CET2M629A5136400	

Date	Expiration	Group	No.	Page
07.2010	07.2012	237	014	2(3)

DESCRIPTION

On the vehicles affected by this bulletin, it is necessary to clean and seal the unit injector harness pass through fitting due to oil seepage.

This bulletin involves Volvo D13 engines with serial number from 916225 up to 931976 included.

Please contact your Prevest Service Center or Authorized Service Provider for additional information and to schedule an appointment at your earliest convenience. Please mention Warranty Bulletin WB10-58. A complete list of the Prevest service points is available on www.prevestcar.com/network.

Prevest Action Service System (PASS) 1 800 463-7738

Regional Service Managers		
Brian Godfroid	Washington State, British Columbia, Alberta, Saskatchewan, Manitoba	1 866 770-8892
Tommy Nolet	New York State, Connecticut, Massachusetts, Vermont, New Hampshire, Rhode Island	1 800 65-PREVO (77386)
Dave Langlois	Delaware, Maryland, Washington DC, Virginia, West Virginia, North Carolina, Michigan, Pennsylvania, New Jersey, Ohio, Kentucky	1 866-95-PREVO (77386)
Kevin Laughlin	Missouri, Illinois, Minnesota, Wisconsin, Iowa, Tennessee, Kansas, Indiana,	1 800 38-PREVO (77386)
James Malcomb	Mississippi, Oklahoma, Texas, Louisiana, Arkansas, Alaska	1 800 83-PREVO (77386)
Tom Munds	Utah, Arizona, Colorado, New Mexico, Nebraska, Idaho, Montana, North Dakota, South Dakota, Wyoming	1 877 55-PREVO (77386)
Fernando Martinez	California, Nevada, Oregon	1 800 95-PREVO (77386)
Bryan Joy	Florida, Georgia, Alabama, South-Carolina	1 866 61-PREVO (77386)
Jean Ruel	Quebec, New Brunswick, Newfoundland, Nova Scotia, Prince Edward Island, Maine	1 800 380-7738
Sylvain St-Amant	Ontario, Quebec	1 888 634-5171
Bill Jensen	Hawaii, Motor Home and shell division	1 800 99-PREVO (77386)

Date	Expiration	Group	No.	Page
07.2010	07.2012	237	014	3(3)

Prevost Service Centers		
Quebec	850, chemin Olivier Saint-Nicolas, Quebec G7A 2N1	Toll free phone: 1-866-870-2046 Tel.: 1-418-831-2046
British Columbia	6537 River Road Delta, BC V4K 5B9	Tel.: 1-604-940-3306
New Jersey	201 South Avenue South Plainfield, New Jersey 07080	Toll free phone: 1-800-223-0830 Tel.: 1-908-222-7211
Florida	6931 Business Park Blvd. North Jacksonville, Florida 32256	Toll free phone: 1-800-874-7740 Tel.: 1-904-886-4555
Tennessee	800 South Cartwright Street Goodlettsville, Tennessee 37072	Toll free phone: 1-877-299-8881 Tel.: 1-615-299-8881
Texas	15200 Frye Road Fort Worth, Texas 76155-2702	Toll free phone: 1-866-773-8678 Tel.: 1-817-685-0250
California	3384 De Forest Circle Mira Loma, California 91752	Toll free phone: 1-800-421-9958 Tel.: 1-951-360-2550

Prevost Parts Customer Service		
US Prevost Parts Customer Service	2200 Point Blvd., Suite 100 Elgin, Illinois 60123	Toll free phone: 1-800-621-5519 Coach Tel.: 1-847-844-7680
Prevost Canadian Parts Customer Service	2955-A, avenue Watt Quebec, Quebec G1X 3W1	Toll free phone: 1-800-463-8876 Phone: 1-418-653-0948 Parts

PROCEDURE

Service technicians, for the complete procedure, refer to Volvo document **FSB237-014, Oil Seepage at Unit Injector Harness Pass-Through Fitting** available on Impact.

ESTIMATED TIME

The estimated time required to perform this warranty bulletin is approximately 0.5 hour if being done simultaneously with other current D13 engine bulletins. As a matter of normal service process, your Prevost Service Center or Authorized Service Provider will also check for other repair measures which might be applicable to your vehicle and this may increase the required total service time.

WARRANTY

This modification is covered by Prevost's normal warranty and will be performed at no charge.

Please contact your Prevost Service Center or your Prevost Certified Service Providers for additional information and to schedule an appointment at your earliest convenience. Please mention WB10-58.

TELL US WHAT YOU THINK!

We are interested in hearing your comments or suggestions regarding this bulletin. Please e-mail them to: TechnicalPublications@volvo.com

Volvo Bus engages in a continuous program of testing and evaluating to provide the best possible product. Volvo Bus, however, is not committed to, or liable for updating existing products.