


PREVOST

Warranty Bulletin

95-29

Date: **July 1995**
Section: **06**
Subject: **LAVATORY NIGHT LIGHT MODIFICATION**
Application:

Model	VIN	
XL-45 Coach	From 2P9L33490S1001497 to 2P9L33496S1001598 incl.	

DESCRIPTION

To improve lavatory lighting, Prévost Car engineering department has modified "Night Light" lighting. It will light up when key is at "ignition" position instead to light up when Marker Lights is on. Proceed as follow to perform this modification.

MATERIAL

Order Prévost # 561790 only if vehicle does not have parcel rack doors.

Parts Prévost #	Description	Qty
561790	Breaker, 6 Amps	1

Note: Material can be obtained through regular channels.

PROCEDURE

Warning: Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Open vehicle rear doors. Open the rear junction box pannel.
2. Disconnect cable # 73 end from terminal #26. Connect cable #73 end to terminal # 48. Refer to sticker 064025 located on right rear door to identify terminal in rear junction box.
3. Only if vehicle does not have parcel rack doors, add the 6 amps breaker CB50. Refer to sticker 064025 to identify breaker location in rear junction box. If vehicle does have parcel rack doors, no breaker has to be installed.

WARRANTY

This modification is covered by the manufacturer's normal warranty. We will reimburse you the part and half an hour (0,5) of labor of labor upon receipt of a completed A.F.A. form on which you must specify as per "Warranty Bulletin 95-29".

Expiration date: July 1996