

# MAINTENANCE INFORMATION

MI20-86

DATE: 11 September 2020 SECTION: 06 ELECTRICAL
SUBJECT: DRL CONNECTION VERIFICATION

First Release 09-22-2020

### **APPLICATION**

AFFEIGATION	
Model	
Volvo 9700	
Model Year : 2020	
VIN: From 3CET2V927L5198317 up to 3CET2W424L5201932.	

#### **DESCRIPTION**

In the vehicles affected by this bulletin, the DRL harness may be incorrectly attached, therefore, it is necessary to verify the harness attachment.

This information only applies whenever needed.

#### **MATERIAL**

Required parts:

Part No.	Description	Qty
563280	FUSE ATM 5A	1

Writer: Francisco Islas

#### **PROCEDURE**



## **DANGER**

Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

1. Open the front hatch.





FIGURE 1

2. Verify all connections.

#### NOTE


Ensure connections are well made.



3. Verify the harness fixation on frame.


#### NOTE

Ensure the 4 fixations are well made.



4. Verify the harness fixation on the reinforcement of co-pilot side. NOTE Ensure the 6 fixations are well made. FIGURE 4 5. Verify the harness fixation on the reinforcement of driver side. NOTE Ensure the 6 fixations are well made. FIGURE 5 **6.** Verify that the fuse (F2) is not blown. NOTE If the fuse is blown, replace it with a new one.

FIGURE 6



## **PARTS / WASTE DISPOSAL**

Discard according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)