



# H3-45, H3-41 BUS



REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
00	2013-01-07	2011099 2012051 2012023	D-2272 D-2364	Preliminary vehicle Start Production	All All	M.P. M.P.	C.L. C.L.	C.L. C.L.
01	2013-05-01	2013050	D-2272	ACM Pwr Relay added	14.3, 5.1	PG	DG	DG
02	2013-10-15	2013037 2013060 2013064	E-2540 E-2540 E-2540	Ricon wheelchair lift lighting Deutsch connectors on Urea system Various harness modifications	0, C1, 14.3, 25.1, 26.3, 35.3, 35.6, 36.1, 37.2, 38.1	Gab	Gab	Clem
03	2013-11-22	2013060	E-2540	Updated Urea system schematic	14.3	Gab	Gab	CLem
04	2014-01-10	2013094 2013108	E-2662	Urea System harness modification S.E. Hvac moved over Evaporator	0, C1, 2.1, 3.1, 5.1, 6.1, 25.1,41.1, 14.3 17.1, 18.2	PG	PG	Clem
05	2014-02-04	2012034	E-2602	GHG14	15.1	SD	SD	CL
06	2014-03-11	2013080	NA	120 VAC Outlets updated	40.1	EL	EL	CL
07	2014-05-21	NA		Pages updated	0, 3.2	SB	CL	CL
08	2014-06-20	2014007	2750	AFSS	0, C1, 5.1,38.1	SB	CL	CL
09	12/09/2014	2014132	2862	Bitzer Compressor	0, C1, E, G, 2.1,15.1, 18.2	EL	CL	CL
10	19/09/2014	2013152	2887	Updated Valve So8	0,C1	SB	CL	CL
11	19/09/2014	2014145	F-2900	Add sunvisor switch on dash board	0, 2.1, 4.1, 19.1, 41.1	MP	CL	CL
12	2015-01-08	2013172 2014122 2015001	F-2923	FRONT PNEUMATIC PLATE, TGW2, OBD15	0, 6.2, 10.1, 12.1, 14.1, 26.1, 32.1, 37.1	Gab	CL	CL
13	2015-01-23	2014122	F-2923	TGW2	0, C1, 41.1, 37.1, G, 33.1	SB	CLEM	CLEM
14	2015-04-08	2014176	G3129	Optimization of interior lighting	0, C1, 22.1, 23.1	SB	CLEM	CLEM
15	2015-04-21	2015003	F-2923	Alt. Pwr Cable #102S=>000 AWG	0, 3.1, 3.2	E.L.	CL	CL



# H3-45, H3-41 BUS



REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CK.	APPR.
16	2015-09-15	2014176 2015147	3129	Optimization of interior lighting Charging system improvements	0, C1, 22.1, 23.1, 5.1, 18.2 0, C1, 3.2, 5.1	SB Gab	CLEM CLEM	CLEM CLEM
17	2015-11-11	2014176		Optimization of interior lighting Update	3.2, 5.1,0	SB	CLEM	CLEM
18	2015-12-08	2015027 2015091	3206	SW LUGG DOOR RELEASE Q4-2015	14.3, 25.1, 10.1, 15.1, 33.1, 32.1, 12.1, 18.2, 17.1, G, 0, C1	SB	CLEM	CLEM
18-1	2016-02-01	2015146	3309	New audio/video system, HHED	0, A, C2, E, G, H, K, L, 3.1, 35.3, 35.6, 35.7, 35.8, 60.2, 60.3, 60.4, 60.5	CLRV	CLEM	CLEM
19	2015-12-14	2015147	G-3325	CHARGING SYSTEM IMPROVEMENTS	0, C1, 3.2, 5.1	Gab	CLEM	CLEM
20	2016-04-06	2016001	G-3367	OBD16	0,C1, 14.3, 11.1	SB	CLEM	CLEM
21	2016-12-15	2016098 2016100 2017001 2016109	H-3735	Amelioration IShift GHG17 New radio GHG17 LTD Extended	0, G, 15.3 C2, 35.6, 35.7 E, 4.1, 16.1, 18.2, 41.1 C1,	GP CLRV SB JL	CLEM	CLEM
22	2017-10-25	2017080	J-3997	LOW PRESS	0,C1, G,18.2	SB	CLEM	CLEM
23	2017-10-27	2017071	J-0083	ELD / ITS GATEWAY	0, A, C1, E, G, J, 2.1, 3.3, 4.1, 6.2, 42.4	GP	JBRI	JBRI