



PREVOST

ENREGISTRÉ - REGISTERED
ISO 9001 & ISO 14001

**MAINTENANCE
INFORMATION**

Mi98-11C



DATE : December 1998	SECTION : 07
SUBJECT : ALLISON TRANSMISSION RECALL CAMPAIGN	

REVISION : C

XL-45 ENTERTAINERS NOW INCLUDED IN ALLISON RECALL CAMPAIGN

APPLICATION

Model	VIN															
XL-40 Coach Model year: 1994 - 1996	From 2P9L33406R <u>1001824</u> up to 2PCL33408T <u>1025690</u> incl.															
XL-45 Coach Model year: 1995 - 1996	From 2P9L33490S <u>1001497</u> up to 2PCL33498T <u>1025736</u> incl.															
XL-45 Entertainer Model year: 1994 - 1995	<table border="0"> <tr> <td>2P9E33492R<u>1001893</u></td> <td>2P9E33498S<u>1001417</u></td> <td>2P9E33498S<u>1001546</u></td> </tr> <tr> <td>2P9E33492R<u>1001925</u></td> <td>2P9E33494S<u>1001443</u></td> <td>2P9E3349XS<u>1001564</u></td> </tr> <tr> <td>2P9E33499R<u>1001971</u></td> <td>2P9E33490S<u>1001458</u></td> <td>2P9E33495S<u>1001567</u></td> </tr> <tr> <td>2P9E33490R<u>1001972</u></td> <td>2P9E33499S<u>1001474</u></td> <td>2P9E33498S<u>1001627</u></td> </tr> <tr> <td></td> <td>2P9E33491S<u>1001498</u></td> <td>2P9E33491S<u>1001632</u></td> </tr> </table>	2P9E33492R <u>1001893</u>	2P9E33498S <u>1001417</u>	2P9E33498S <u>1001546</u>	2P9E33492R <u>1001925</u>	2P9E33494S <u>1001443</u>	2P9E3349XS <u>1001564</u>	2P9E33499R <u>1001971</u>	2P9E33490S <u>1001458</u>	2P9E33495S <u>1001567</u>	2P9E33490R <u>1001972</u>	2P9E33499S <u>1001474</u>	2P9E33498S <u>1001627</u>		2P9E33491S <u>1001498</u>	2P9E33491S <u>1001632</u>
2P9E33492R <u>1001893</u>	2P9E33498S <u>1001417</u>	2P9E33498S <u>1001546</u>														
2P9E33492R <u>1001925</u>	2P9E33494S <u>1001443</u>	2P9E3349XS <u>1001564</u>														
2P9E33499R <u>1001971</u>	2P9E33490S <u>1001458</u>	2P9E33495S <u>1001567</u>														
2P9E33490R <u>1001972</u>	2P9E33499S <u>1001474</u>	2P9E33498S <u>1001627</u>														
	2P9E33491S <u>1001498</u>	2P9E33491S <u>1001632</u>														
"H3" series coaches EXCEPT H3-40 coaches Model year: 1994 - 1996	<p>2P9H33495R<u>1001012</u></p> <p>AND</p> <p>From 2P9H33494R<u>1001020</u> up to 2PCH33411T<u>1011385</u> incl.</p>															

DESCRIPTION :

Apply modifications to all the aforementioned vehicles in accordance with the attached Allison Transmission campaign bulletin (97C7).