

Cust Adapt. Move alternators on cold side (Small AC not installed at delivery)

Refer to P18.3 STD for all details

