

**PREVOST**

ENREGISTRÉ - REGISTERED  
ISO 9001 & ISO 14001

**WARRANTY  
BULLETIN**



Wb10-03A



<b>DATE :</b> MAY 2010	<b>SECTION :</b> 01 - Engine
<b>EXPIRATION:</b> MAY 2012	
<b>SUBJECT :</b> VOLVO D13 ENGINE ADDITION OF AN AIR PRESSURE RELIEF VALVE ON THE AFTERTREATMENT FUEL INJECTOR (AFI) AIR CIRCUIT	

<b>REVISION : A THIS WARRANTY BULLETIN SUPERSEDES PREVIOUS VERSION.</b>
<b>Addition of text mentioning that this document is available on Volvo's "Trucks Dealer Portal "</b>

**APPLICATION**

Model	VIN		
H3-41, H3-45 coaches  Model Year : 2008 – 2010	2PCH334948C710995	2PCH334919C711359	2PCH334969C711437
	2PCH334988C711096	2PCH3349X9C711361	2PCH3349X9C711439
	2PCH334938C711202	2PCH334999C711366	2PCH334939C711444
	2PCH334928C711207	2PCH334909C711367	2PCH334979C711446
	2PCH334938C711216	2PCH334989C711374	2PCH334929C711449
	2PCH334928C711224	2PCH3349X9C711375	2PCH334999C711450
	2PCH334918C711232	2PCH334979C711379	2PCH3341X9C711452
	2PCH334928C711241	2PCH334169C711383	2PCH334939C711461
	2PCH334978C711249	2PCH334929C711385	2PCH334929C711466
	2PCH334948C711256	2PCH334949C711386	2PCH334969C711468
	2PCH334918C711263	2PCH334139C711387	2PCH33496AC711474
	2PCH334928C711272	2PCH334969C711390	2PCH33491AC711477
	2PCH334998C711303	2PCH334979C711396	2PCH33499AC711484
	2PCH3349X9C711313	2PCH334999C711402	2PCH33490AC711485

	2PCH334909C711322	2PCH334919C711409	2PCH3341XAC711486
	2PCH334969C711325	2PCH334939C711413	2PCH33498AC711489
	2PCH3349X9C711327	2PCH334169C711416	2PCH33494AC711490
	2PCH334949C711341	2PCH334929C711418	2PCH33491AC711494
	2PCH334989C711343	2PCH334949C711422	2PCH33494AC711506
	2PCH334919C711345	2PCH334969C711423	2PCH33496AC711507
	2PCH334959C711347	2PCH334989C711424	2PCH33498AC711508
	2PCH334999C711349	2PCH334939C711427	2PCH3349XAC711509
	2PCH334949C711355	2PCH334959C711428	2PCH33496AC711510
	2PCH334969C711356	2PCH334959C711431	
	2PCH334989C711357	2PCH334929C711435	
X3-45 coaches & XLII-45 Entertainer  Model Year : 2008 - 2010	2PCG334908C729295	2PCY334999C729625	2PCY334959C729668
	2PCY334979C729591	2PCY334969C729629	2PCY334949C729726
	2PCG3349X9C729614	2PCY334949C729631	2PCG334909C729752
	2PCY3349X9C729620	2PCY3349X9C729634	2PCG334999C729765
	2PCY334939C729622	2PCY334999C729642	

## DESCRIPTION

On the vehicles affected, it is necessary to install an air pressure relief valve on the air circuit connected to the aftertreatment fuel injector. Air under pressure may flow upstream in the fuel supply line when the engine is not running. This may cause difficult engine start. For this reason, it is very important to have this corrective measure performed as soon as possible.

Warranty bulletin Wb10-03 is a supplement to warranty bulletin Wb08-19. Wb08-19 must have been completed prior execution of Wb10-03.

You must make an appointment at one of PrevoSt Service Centers or PrevoSt Certified Service Providers. Please, contact your PrevoSt Regional Service Manager to find out the nearest service center location or refer to **Parts and Service** tab on PrevoSt web site or go to [www.prevoStcar.com/network](http://www.prevoStcar.com/network) for the list of the nearest PrevoSt Certified Service Providers.

**PrevoSt Action Service System (PASS) 1 800 463-7738**

<b>Regional Service Managers</b>		
Brian Godfroid	Washington State, British Columbia, Alberta, Saskatchewan, Manitoba	1 866 770-8892
Tommy Nolet	New York State, Connecticut, Massachusetts, Vermont, New Hampshire, Rhode Island	1 800 65-PREVO (77386)
Dave Langlois	Delaware, Maryland, Washington DC. Virginia, West Virginia, North Carolina, Pennsylvania, New Jersey, Ohio, Kentucky	1 866-95-PREVO (77386)
Kevin Laughlin	Missouri, Illinois, Minnesota, Wisconsin, Iowa, Tennessee, Kansas, Indiana, Michigan	1 800 38-PREVO (77386)
James Malcomb	Mississippi, Oklahoma, Texas, Louisiana, Arkansas, Alaska	1 800 83-PREVO (77386)
Tom Munds	Utah, Arizona, Colorado, New Mexico, Nebraska, Idaho, Montana, North Dakota, South Dakota, Wyoming	1 877 55-PREVO (77386)
Fernando Martinez	California, Nevada, Oregon	1 800 95-PREVO (77386)
Bryan Joy	Florida, Georgia, Alabama, South-Carolina	1 866 61-PREVO (77386)
Jean Ruel	Quebec, New Brunswick, Newfoundland, Nova Scotia, Prince Edward Island, Maine	1 800 380-7738
Sylvain St-Amant	Ontario, Quebec	1 888 634-5171
Bill Jensen	Hawaii, Motor Home and shell division	1 800 99-PREVO (77386)

<b>Prevost Service Centers</b>		
Quebec	850, chemin Olivier Saint-Nicolas, Quebec G7A 2N1	Toll free phone: 1-866-870-2046 Tel.: 1-418-831-2046 Fax: 1-418-831-7432
British Columbia	6537 River Road Delta, CB V4K 5B9	Tel.: 1-604-940-3306 Fax: 1-604-940-3384
New Jersey	201 South Avenue South Plainfield, New Jersey 07080	Toll free phone: 1-800-223-0830 Tel.: 1-908-222-7211 Fax: 1-908-222-7304
Florida	6931 Business Park Blvd. North Jacksonville, Florida 32256	Toll free phone: 1-800-874-7740 Tel.: 1-904-886-4555 Fax: 1-904-886-0092 Administration Fax: 1-904-886-0093 Parts
Tennessee	800 South Cartwright Street Goodlettsville, Tennessee 37072	Toll free phone: 1-877-299-8881 Tel.: 1-615-299-8881 Fax: 1-615-299-8816
Texas	15200 Frye Road Fort Worth, Texas 76155-2702	Toll free phone: 1-866-773-8678 Tel.: 1-817-685-0250 Fax: 1-817-685-0460
California	3384 De Forest Circle Mira Loma, California 91752	Toll free phone: 1-800-421-9958 Tel.: 1-951-360-2550 Fax: 1-951-360-2560 Administration Fax: 1-951-360-2565 Parts

## PROCEDURE

Service technicians, for the complete procedure, refer to *Service Center Information* [Sci10-22](#) available on:

- 1) Prevost service portal under **Service/Service Tips/Service Center Information**
- 2) Volvo's « TRUCKS DEALER PORTAL » under **Prevost > service > publications**

## WARRANTY

This modification is covered by Prevost's normal warranty and will be performed at no charge.

The working time required to perform this warranty bulletin is approximately 2 hours. As a matter of normal service process, your Prevost Service Center or Prevost Certified Service Providers will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

Please contact your Prevost Service Center or your Prevost Certified Service Providers for additional information and to schedule an appointment at your earliest convenience. Please mention WB10-03A.