

# H3-45 VIP

REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CHECKED	APPROVED
0	2018-03-15	2015007	J-0113 J-0155 K-0295	SMALL A/C PRELIMINARY FULL A/C PRELIMINARY START OF PRODUCTION	ALL	M.P.	C.Lem.	C.Lem.
1	2018-05-25	2018011	K-0369	RELS UPDATE	0, 15.1, C1, G 3.2	G.P.	C.Lem.	C.Lem.
2	2018-06-21	2018087	K-0387	RH Console switches for driver's lights	0, 2.1, 4.2, 19.1, 25.1, 33.1, G	E.L.	C.Lem.	C.Lem.
3	2018-10-05	2018087	K-0503	Effective VIN correction K-0387 is a preliminary	0,19.1	E.L.	C.Lem.	C.Lem.
4	2019-01-08	2018055	K-0605	OBD19	0, 2.1, 8.1, 14.1, 14.2, 15.1, C1, G, H	G.P.	C.Lem	C.Lem
		2018110	K-0605	GIGAVAC	3.1	G.P.	C.Lem	C.Lem
5	2019-07-04	2019093		Dashboard Foot Damper Obsolescence	0, G, 18.1	Gab	C.Lem.	C.Lem.
	2019-07-04	2018149	L-0909	TPMS Gateway UPDATE	6.2, 39.1 19.1	Gab E.L.	A.B.	A.B.
6	2020-02-14	2020002	L-1055	Urée PWR	0, 3.1, 5.1, 14.2, C1, G	S.B.	C.Lem.	C.Lem.
7	2020-03-18	2019037	L1138	Driver Assist	0,A,C1,2.1,4.1,6.2,10.1, 16.2,39.1	M.P.	M.L	M.L
				Digital driver light dimmer	19.1	G.P.		
8	2021-01-15	2021001	1154	OBD21, VECU5	0,3,2,4.1,5.1,6.2,12.1,14.1,C1,G	S.B.	C.Lem.	C.Lem.

	WIRING DIAGRAM	DWG NO.:D061760 p0.1	REV.: 11
--	----------------	----------------------	----------

# H3-45 VIP

REV.	DATE	O.C.	EFF.	DESCRIPTION	PAGE(S)	BY	CHECKED	APPROVED
9	2021-04-15	2021001		UPDATE	0,29.1	S.B.	G.P	G.P
10	2021-06-18	2021072		eMirror ready Gateway Module	0,2.1, 4.2, 31.2	S.C	M.L.	M.L.
11	2021-12-13	2022001		OBD22	0, C1, G, 14.2	S.B.	G.P.	G.P.

	WIRING DIAGRAM	DWG NO.: D061760 p0.2	REV.: 11
--	----------------	-----------------------	----------