



PREVOST

SAFETY RECALL

SR22-312

DATE :	June 2022	SECTION: 06 ELECTRICAL
SUBJECT:	LOOSE CONNECTIONS ON ALTERNATOR CABLES – MAIN POWER COMPARTMENT	

First Release

June 2022

DESCRIPTION

This Safety Recall applies to MTA/NYCT X3-45 Commuters.

PrevoSt has released Special Bulletin SP22-301 to remedy the vehicles potentially affected to ensure the power cables in the rear junction box are properly tightened.

Applicable vehicles are notified under SP22-301.

NHTSA SAFETY RECALL #22V-179

